Office of Froz Culture

Office of Froz Culture

FEB 10 2008

LOUIS E GITOMER

LOU_GITOMER@VERIZON NET PUBLIC PROOF

LAW OFFICES OF LOUIS E. GITOMER

221650

THE ADAMS BUILDING, SUITE 301
600 BALTIMORE AVENUE
TOWSON, MARYLAND 21204-4022

(202) 466-6532 FAX (410) 332-0885

February 20, 2008

Honorable Anne K. Quinlan Acting Secretary Surface Transportation Board 395 E Street, S.W. Washington, D. C. 20423

RE: Docket No. ΛB-364 (Sub-No. 14X). Mid-Michigan, Railroad, Inc. Abandonment Exemption—in Kent, Ionia, and Monical m. Colinius.

MI

Dear Acting Secretary Quinlan:

Enclosed are the original and 10 copies of a Petition for Exemption for the Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 26.40-mile rail line between Lowell, milepost 103.20, and Greenville, milepost 78.50, at the end of the line in Kent, Ionia, and Montealm Counties, MI. Also enclosed are a check from MMRR for the filing fee of \$5.400, and a computer diskette containing the Petition in Word and pdf format. All of the color Exhibits are attached to the end of the Petition in Exhibit J.

Please time and date stamp the additional copy of this letter and the Petition and return them with our messenger Thank you for your assistance.

is E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

If you have any questions please call or email me.

FILED

FEB 2 0 2008

SURFACE TRANSPORTATION BOARD

Enclosures

FEB 2 0 2008
SUHFACE
TRANSPORTATION BOARD

BEFORE THE SURFACE TRANSPORTATION BOARD

221650

Docket No AB-364 (Sub-No. 14X)

MID-MICHIGAN RAILROAD, INC.-ABANDONMENT EXEMPTION-IN KENT, IONIA, AND MONTCALM COUNTIES, MI

PETITION FOR EXEMPTION

Office LEB 2 Orlings



FILED

FEB 2 0 2008

SURFACE TRANSPORTATION BOARD

Scott G. Williams, Esq.
Scnior Vice President and General Counsel
RailAmerica. Inc.
5300 Broken Sound Boulevard N.W
Second Floor
Boca Raton, FL 33487
(561) 226-1757

Louis E. Gitomer, Esq. Law Offices of Louis E. Gitomer 600 Baltimore Avenuc Suite 301 Towson, MD 21204 (202) 466-6532

Dated: February 20, 2008

Attorneys for: MID-MICHIGAN RAILROAD, INC.

BEFORE THE SURFACE I'RANSPORTATION BOARD

-	Docket No. AB-364 (Sub-No. 14X)	
	I RAILROAD, INC.– ABANDONMENT EXEMP T, IONIA. AND MONTCALM COUNTIES, MI	TION–

PETITION FOR EXEMPTION

Mid-Michigan Railroad, Inc. ("MMRR") petitions the Surface Transportation Board ("Board") to exempt, under 49 U.S.C. § 10502, MMRR's abandonment of a 24.70-mile rail line between Lowell, milepost 103.20, and Greenville, milepost 78 50, at the end of the line in Kent, Ionia, and Montealm Counties, MI (the "Line") from the prior approval requirements of 49 U.S.C. §§ 10903 and 10904. MMRR also requests the Board to establish a procedural schedule.

Abandonment will allow MMRR to avoid costs incurred by continued ownership of the Line. MMRR has entered a Memorandum of Understanding (the "MOU) to sell the Line to West Michigan Trails and Greenways Coalition ("WMTGC") for interim trail use/rail banking. No traffic moved over the Line in 2007, and none has moved over the Line to date in 2008. Crop Production Services ("CPS")², the last shipper on the Line, received one shipment in December 2006. There is no longer a demand for rail service.

² 6288 South Greenville Road, Greenville, MI 48838, Milepost 79.8.

¹ The Board rejected the same abandonment for omitting an affected county. *Mid-Michigan Railroad, Inc —Abandonment Exemption—in Kent and Montcalm Counties, MI*, STB Docket No. AB-364 (Sub-No. 11X) (STB served January 25, 2008) ("*MMRR1*"). In the instant Petition, MMRR has included Ionia County and provided the required notice.

PROPOSED TRANSACTION

MMRR proposes to abandon the 24.7-mile rail line between Lowell, milepost 103 20, and Greenville, milepost 78.50, at the end of the line in Kent, Ionia, and Montealm Counties. MI. The Line traverses Zip Codes 48809, 48838, 48887, and 49331. A colored map of the Line is attached as Exhibit A (and at the end of this pleading). Exhibit B consists of the Combined Environmental and Historic Report. The draft Federal Register Notice is in Exhibit C, and copies of the newspaper publication and the required certification are in Exhibit D. The certificate of service is in Exhibit E. Exhibit F contains the Verified Statement of Mark D. Garvin, Chief Engineer for all of the subsidiary railroads of RailAmerica, Inc. Mr. Garvin addresses that value of the track and material on the Line, the need for rehabilitation, and the cost of maintenance. Exhibit G contains the Verified Statement of Mr. Robert M. Frelich, Jr., and addresses the costs of operating over the Line. In Exhibit H, Mr. Todd N. Cecil, Vice President-Real Estate, presents the value of the real estate. In Exhibit I, Mr. Robert Dine concludes that no traffic has moved over the Line since 2006 and that shippers currently served in Lowell are not located on the Line and will continue to receive service

Based on information in MMRR's possession, the Line does not contain federally granted right-of-way Any documentation in MMRR's possession concerning title will be made available to those requesting it. There are stations at Lowell, Belding, and Greenville

BACKGROUND

MMRR acquired the Line from CSX Transportation, Inc. and began operating in 1987.³

In the first full year of operations, the Line generated about 3,500 carloads. Traffic on the Line

³ Mid-Michigan Railroad, Inc.—Acquisition and Operation Exemption—CSX Transportation, Inc., ICC Finance Docket No. 31189 (ICC served January 7, 1988)

has declined to the point where no traffic moved in 2007 and no traffic has moved to date in 2008

Prior to April 2006. Frigidaire Corporation ("Frigidaire") was an active shipper on the Line. Through March 2006, Frigidaire had made 98 shipments on the Line. In 2005 Frigidaire had made 1,002 shipments on the Line and in 2004 Frigidaire made 846 shipments on the Line. Frigidaire closed its facility on the Line in April 2006 and moved the manufacturing to Mexico and South Carolina. Frigidaire has not shipped over the Line since March 2006. MMRR does not expect Frigidaire to use the Line in the future.

CPS made one shipment over the Line in December 2006. CPS did not use the Line in 2007 or 2008 to date, nor has any other shipper. Therefore, MMRR is projecting Forecast Year traffic at one car per year by excluding the Frigidaire traffic that has been permanently diverted from the Line and including the CPS traffic.

The Line did not generate any freight in 2007. The Line is listed as Federal Railroad Administration ("FRA") Class I track. As described below, abandoning the Line will permit MMRR to save (1) rehabilitation costs of \$125,000, (3) the annual maintenance costs of the Line of \$123,500 and (4) opportunity costs of \$656,811. MMRR will salvage the track and materials, which have an estimated net liquidation value of \$2,460,077. In addition, MMRR intends to sell the Line for interim trail use/rail banking to WMTGC. The value of the real estate is about \$1,288,000 based on the negotiations conducted by Mr. Cecil (See Exhibit H) and Mr. Cecil's expert analysis of the valuation of real estate.

Upon receipt of abandonment authority. MMRR plans to salvage the track and materials on the Line, but leave the ties, bridges, and culverts necessary for interim trail use/rail banking in

place as per the MOU with WMTGC. Some of the track and materials will be sold as scrap and the remainder will be used by MMRR and its railroad affiliates. MMRR will sell the real estate to WMTGC to convert the active rail line to interim trail use/rail banking.

A. There is no traffic on the Line.

Iraffic on the Line has seen a precipitous decrease since MMRR acquired the Line. In its first year of operation in 1988, the Line generated about 3,500 carloads. There was no traffic on the Line in 2007 and none to date in 2008. The last carload on the Line moved in December 2006. Frigidaire, the largest shipper on the Line, closed its facility in April 2006 and stopped using the Line.

Because of the lack of traffic, MMRR is burdened with retaining a rail line that does not generate any rail freight revenue.

B. MMRR will incur costs to rehabilitate the Line.

The Line is currently in FRA Class I condition. Since there has been no traffic over the Line since December 2006, MMRR has deferred maintenance on the Line. In his attached Verified Statement, Mr. Garvin explains that to keep the Line in FRA Class I condition, MMRR will be required to make \$125.000 in capital expenditures to rehabilitate the Line.

C. MMRR will incur costs to maintain the Line.

The Line is 24.70 miles in length. The Board has accepted a range of normalized maintenance of way costs of between \$4.300 and \$6,000 in recent decisions ⁵ MMRR will adopt

⁴ MMRR has served a copy of this Petition on CPS.

⁵ Wisconsin Central Ltd –Abandonment–in Ozaukee, Sheboygan and Manitowoc Counties, WI, STB Docket No. AB-303 (Sub-No. 27), STB served October 18, 2004, at 8; and Minnesota Northern Railroad, Inc –Abandonment Exemption–in Polk and Norman Counties. MN. STB Docket No. AB-497 (Sub-No. 3x) (STB served December 4, 2006), at 2

a conservative annual normalized maintenance cost of \$5,000 per mile ⁶ Mr. Garvin has reviewed an annual average \$5,000 per mile normalized maintenance cost and found it to be in line with the maintenance costs incurred across the MMRR. Therefore, after MMRR makes the expenditure to eliminate deferred maintenance on the Line, MMRR will incur annual maintenance costs for the Line of about \$123,500.

D. Calculation of opportunity costs.

Opportunity costs (or total return on value of road property) reflect the economic loss experienced by a carrier from forgoing a more profitable alternative use of its assets. Under Abandonment Regulations—Costing, 3 I.C.C.2d 340 (1987), the opportunity cost of road property is computed on an investment base equal to the sum of: (1) allowable working capital; (2) the net liquidation value (NLV) of the line; and (3) current income tax benefits (if any) resulting from abandonment. The investment base (or valuation of the road properties) is multiplied by the current nominal rate of return, to yield the nominal return on value. The nominal return is then adjusted by applying a holding gain (or loss) to reflect the increase (or decrease) in value a carrier will expect to realize by holding assets for 1 additional year.⁷

1. Calculation of net salvage value ("NSV").

Mr. Garvin is responsible for the development of maintenance and rehabilitation plans for RailAmerica's subsidiary railroads. Based on MMRR's records, an inspection of the Line, the latest costs of rail materials, and the cost of removal and transportation, Mr. Garvin calculates the NSV of the Line to be \$2,460,077 (See Exhibit 1 and the Exhibit thereto)

2. Calculation of the value of real estate ("VRE").

The VRE has been calculated by Mr Cecil to be \$1,288,000, based on the MOU and Mr Cecil's vast experience. Hence, the net liquidation value ("NLV") of the Line is \$3,748,077.

⁶ Central Michigan Railway Company-Abandonment Exemption-in Saginaw County, MI, STB Docket No. AB-308 (Sub-No. 3X) (STB served October 31, 2003), at 5.

⁷ Wisconsin Central Ltd –Abandonment–in Ozaukee, Sheboygan and Manitowoc Counties, WI, STB Docket No AB-303 (Sub-No. 27) (STB served October 18, 2004). at 10-11.

3. Calculation of 15 days working capital.

Mr Frelich calculated the cost of operating the Line to be \$1,410 per year. Working capital for the computation of opportunity costs is calculated as 15 days of the costs of the Line. Therefore, MMRR has totaled the operating costs and maintenance costs (\$124,910), divided them by 365 and multiplied that amount by 15 to arrive at the 15 days of working capital of \$5.133.

4. Nominal cost of capital.

The Board has recently accepted the nominal cost of capital for a Class III railroad of 17.50 percent. Therefore, MMRR has decided to use 17.50 percent as the nominal cost of capital in calculating the opportunity costs of the Line.

5. Income tax consequences.

The book value of the Line is \$3,748,077. The NLV of \$3,748,077 less the book value yields no gain. Therefore, sale of the Line will have no tax consequences

6. Holding gain.

Because of the volatility of the market for scrap and reusable steel and the decline in the market for real estate, MMRR estimates that there will be no holding gain or loss in the current economic environment. The Board has accepted such an analysis.

⁸ Southwestern Railroad Company, Inc –Abandonment Exemption–in Ellis County, OK, and Lipscomb, Ochiltree, and Hansford Counties, TX, STB Docket No. AB-341 (Sub-No. 1X) (STB served November 20, 2007).

⁹ Southwestern Railroad Company. Inc -Abandonment Exemption-in Ellis County, OK, and Lipscomb, Ochiltree, and Hansford Counties, TX, STB Docket No. AB-341 (Sub-No. 1X) (STB served November 20, 2007) at 2.

7. Calculation of Opportunity Costs.

The following Table shows the opportunity cost calculation.

Working Capital	\$	5,133
NLV	\$3,	748,077
Гахеs	\$	0
Holding Gain	\$	0
Valuation	\$3,753,210	
Nominal Rate of Return	17.	50%

17.5070

Opportunity Cost \$ 656,811

E. Alternate transportation.

There are numerous roads crossing and paralleling the Line between Lowell and Greenville. The main highways serving the same area as the Line are Michigan Routes 21, 44, 57, and 91, as well as local roads. The limited traffic that the Line carried has found alternates to rail transportation as demonstrated by the decline in traffic. Therefore, there is alternate transportation service available.

F. Summary.

Continued ownership and operation of the Line by MMRR will continue to be a burden on MMRR and interstate commerce MMRR will incur rehabilitation costs of \$125,000, annual maintenance costs of \$123,500, and opportunity costs of \$656,811 MMRR will be able to sell the real estate for interim trail use/rail banking for about \$1,288,000 and will be able to reuse or sell the track and materials, which is valued at about \$2,460,077. In addition, there is alternate transportation service available.

There will be minimal, if any, harm to rail shippers who have not used the Line in 2007 or 2008. Traffic has been declining over the years and dropped precipitously when Frigidaire relocated its plant from Greenville.

MMRR contends that in balancing the harm to it and interstate commerce against the harm to shippers and local interests, the balance clearly favors abandonment.

ARGUMENT SUPPORTING THE ABANDONMENT

MMRR seeks an exemption under 49 U.S.C. § 10502 from the applicable requirements of 49 U.S.C. §§ 10903 and 10904 in order to abandon the Line and convert it to interim trail use/rail banking.

Under 49 U.S.C. § 10502, the Board must exempt a transaction from regulation when it finds that:

- (1) regulation is not necessary to carry out the rail transportation policy of 49 U.S.C. § 10101; and
 - (2) either:
 - (a) the transaction is of limited scope, or
 - (b) regulation is not necessary to protect shippers from the abuse of market power.

The legislative history of Section 10502 reveals a clear Congressional intent that the Board should liberally use its exemption authority to free certain transactions from the administrative and financial costs associated with continued regulation. In enacting the Staggers Rail Act of 1980, Pub. I. No. 96-488, 94 Stat. 1895, Congress encouraged the Board's predecessor agency to liberally use the expanded exemption authority under former Section 10505.

The policy underlying this provision is that while Congress has been able to identify broad areas of commerce where reduced regulation is clearly warranted, the Commission is more capable through the administrative process of examining specific regulatory provisions and practices not yet addressed by Congress to determine where they can be deregulated consistent with the policies of Congress. The conferees expect that, consistent with the policies of this Act, the Commission will pursue partial and complete exemption from remaining regulation.

H.R Rep No. 1430, 96 the Cong. 2d Sess. 105 (1980). See also Exemption From Regulation—Boxear Traffic, 367 I.C.C. 424, 428 (1983), vacated and remanded on other grounds, Brae Corp v United States, 740 F.2d 1023 (D.C. Cir 1984). Congress reaffirmed this policy in the conference report accompanying the ICC Termination Act of 1995, Pub. L. No. 104-88, 109 Stat. 803, which re-enacted the rail exemption provision as Section 10502. H.R. Rep. No. 422, 104th Cong., 1st Sess. 168-69 (1995).

A. The Application of 49 U.S.C. § 10903 Is Not Necessary to Carry Out the Rail Transportation Policy

Detailed scrutiny of this transaction is not necessary to carry out the rail transportation policy. An exemption would minimize the unnecessary expense associated with the preparation and filing of a formal abandonment application, expedite regulatory decisions and reduce regulatory barriers to exit. 49 U.S.C. § 10101 (2) and (7). The abandonment by MMRR will not result in a loss of rail service. CSP, the last shipper on the Line, has not used rail service over the Line since December 2006. The other shipper on the Line, Frigidaire closed its facility on the Line in March 2006 and stopped using the Line. The purchaser of the Frigidaire facility has made no arrangements for rail service.

MMRR will avoid rehabilitation costs of \$125,000, annual maintenance costs of \$123,500, and opportunity costs of \$656,811. MMRR will receive \$2,460,077 for salvaging the track and material in the Line and \$1,288,000 for the real estate. The Line will be converted to

interim trail use/rail banking. Granting this exemption, therefore, fosters sound economic conditions and encourages efficient management by permitting the rationalization of an unnecessary rail line. 49 U.S.C. § 10101 (3), (5) and (9). Other aspects of the rail transportation policy are not adversely affected. For example, competition and the continuation of a sound rail transportation system are not affected since the public will not be deprived of any needed rail services.

B. This Transaction Is Of Limited Scope

The proposed transaction is of limited scope. MMRR seeks to abandon a 24.70-mile line in three counties and two cities in Michigan.

C. This Transaction Will Not Result In An Abuse Of Market Power.

MMRR is abandoning the Line. There are no active shippers located on the Line. CPS. the only shipper on the Line, has not shipped over the Line since December 2006.

Since no shipper will lose service, MMRR does not anticipate any opposition to the proposed abandonment.

THE ABANDONMENT SHOULD BE EXEMPTED FROM THE OFFER OF FINANCIAL ASSISTANCE PROVISIONS

There has been no rail service over the Line since December 2006, when one carload moved on the Line. The main user of the Line closed its facility in April 2006. WMTGC has entered a MOU to acquire the Line from MMRR for interim trail use/rail banking. It is obvious that the Line is no longer required to provide common carrier service and there is another public use for the Line.

The Board has often observed that the offer of financial assistance ('OFA") process takes priority over converting a rail line to interim trail use/rail banking. "OFAs to acquire rail lines

for continued rail service or to subsidize rail operations take priority over interim trail use/rail banking."10

Permitting the abandonment to become effective without application of the OFA process will minimize the need for federal regulatory control over the rail system, expedite the Board's regulatory decisions, and reduce the regulatory barriers to exit from unprofitable rail service 49 U.S.C. § 10101(2) and (7). The Board and its predecessor, the Interstate Commerce Commission have granted exemptions from 49 U.S.C. § 10904 (previously 49 U.S.C. § 10905) (the "OFA Provisions") where the right-of-way is needed for a valid purpose and there is no overriding public need for continued rail service. ¹¹ There is a MOU for MMRR to sell the Line to WMTGC for the public purpose of converting it to interim trail use/rail banking. In the event the Line is needed for rail service in the future, the rail banked Line could be returned to rail service.

The Line has not been used since December 2006. The imposition of the OFA Provisions would delay or could completely frustrate the acquisition of the Line for the purpose of interim trail use/rail banking. The acquisition could be delayed for at least six months, if not more if this abandonment were subjected to the OFA Provisions. During this time, MMRR would continue to incur substantial opportunity costs. The Line is not needed for common carrier rail service. It is appropriate for the Board to foster the conversion of this active rail line to interim trail use/ rail banking by exempting this abandonment from the OFA Provisions. The Board has stated "We

¹⁰ Rail Abandonments-Use of Rights-of-Way As Trails, 2 I.C.C.2d 591, 608 (1986).

[&]quot;See, Doniphan, Kensett and Searcy Railway—Abandonment Exemption - In Searcy, White County, AR, STB Docket No. AB-558X (STB served May 6, 1999); Union Pacific Railroad Company—Abandonment Exemption—In Salt Lake County, UT, STB Docket No. AB-33 (Sub-No. 116X) (STB served September 30, 1998); K & E Railway Company—Abandonment Exemption—In Alfalfa, Garfield, and Grant Counties, OK and Barber County, KS, STB Docket No. AB-480X (STB served December 31, 1996); and Southern Pacific Transportation

have granted exemptions from these provisions from time to time, when appropriate." MMRR contends that the proposal here is appropriate for an exemption from the OFA Provisions.

Because there are no longer any rail transportation customers on the Line, it is clear that the proposed exemption from 49 U.S.C. § 10904 presents no opportunity for an abuse of market power. Exemption from the OFA Provisions is also limited in scope because MMRR seeks the exemption for a 24.70-mile line in two counties and in one state, Michigan.

REQUEST FOR PROCEDURAL SCHEDULE

MMRR respectfully requests the Board to adopt a procedural schedule in this proceeding permitting any party to submit a reply to the Petition, as a matter of right, and permitting MMRR to file rebuttal to those replies as a matter of right. In MMRR1, the Board relied upon unverified comments filed by the Michigan Department of Transportation, to which MMRR had no right to respond.

MMRR contends that the Board's rules at 49 C.F.R. §§ 1152.60 (the "Abandonment Exemption Rules"), 1121 (the "Exemption Rules"), and 1112 (the "Modified Procedure Rules") as well as 49 U.S.C. § 10502 permit the opening of the type of proceeding proposed by MMRR.

MMRR is requesting the Board to commence a proceeding and establish a procedural schedule so that any party seeking to comment on the proposed abandonment has a right to comment and submit evidence, and so that MMRR has an opportunity to respond. MMRR believes that the proposed abandonment may generate comments.

¹² CSX Transportation, Inc –Abandonment Exemption–in Genesee County, MI, STB Docket No. AB-55 (Sub-No. 633X) (STB served July 25, 2007).

Company—Discontinuance of Service Exemption—In Los Angeles County, CA, ICC Docket No. AB-12 (Sub-No. 172X) (ICC served December 23, 1994).

MRR has been advised that the Frigidaire facility has been sold to a party that may be interested in rail service. However, MMRR has not been contacted concerning providing rail service, nor has MMRR been advised of the commodity to be shipped and the number of carloads that might be shipped or when rail service would begin. Speculation about future traffic does not relieve MMRR of the burden of continued ownership of the Line. However, MMRR should be permitted to respond to whatever, if any, comments are submitted. The Board can avoid additional petitions for leave to respond by opening a proceeding.

Under 49 U.S.C. § 10502(b), the "Board may, where appropriate, begin a proceeding under this section on its own initiative or on application by ... an interested party." MMRR contends that it is appropriate to begin a proceeding in this matter

The Board has adopted special rules applicable to petitions for exemption involving the abandonment of a rail line 49 C.F.R. §1152.60. Procedurally, those rules require that within 20 days of the filing of the petition, the Board, through the Director of the Office of Proceedings, will publish a notice of the filing in the *Federal Register*. 49 C.F.R. §1152.60(a). Where the Abandonment Exemption Rules are not in conflict with the Exemption Rules, the Exemption Rules apply. *Id.* Under the Exemption Rules "the Board may consider during its deliberation any public comments filed in response to a petition for exemption." 49 C.F.R. §1121.4(a). The Exemption Rules also permit the Board to "[d]irect that additional information be filed." 49 C.F.R. §1121.4(c)(1)(i). The Modified Procedure Rules permit the Board to develop a record in writing (49 C.F.R. § 1112.1) and set out a schedule (49 C.F.R. § 1112.2).

MMRR is requesting the Board to give effect to all of these rules and adopt a schedule similar to that used in abandonment application proceedings. See 49 C.F.R. § 1152.26(a).

.

MMRR proposes that the Board adopt and publish in the notice in the *Federal Register*, the following schedule:

February 20, 2008—Petition for Exemption filed.

March 11, 2008—Due date for Notice of Petition to be published in the Federal Register.

April 4, 2008—Due date for protests and comments, including opposition case in chief, and for public use and trail use requests.

April 18, 2008—Due date for MMRR's reply to opposition case and for MMRR's response to trail use requests.

June 6, 2008—Due date for service of decision on the merits.

June 16, 2008—Due date for offers of financial assistance, unless exempted by the Board.

MMRR's request is consistent with the Board's recent practice. The Board instituted a proceeding upon the request of the petitioner, established a procedural schedule permitting interested parties to submit comments, and permitted the petitioner to respond as a matter of right MMRR seeks the same relief here.¹⁴

MMRR has presented its case-in-chief in this Petition. MMRR respectfully requests the Board to notify potential parties in the *Federal Register* notice that a procedural schedule is being adopted similar to the one used for abandonment applications

COMBINED ENVIRONMENTAL AND HISTORIC REPORT

A Combined Environmental and Historic Report is in Exhibit B.

FEDERAL REGISTER NOTICE

A draft Federal Register notice is attached hereto as Exhibit C.

¹³ See, e.g Chicago, R I & P R Co. Abandonment, 363 I.C.C. 150 (1980).

LABOR PROTECTION

The interests of railroad employees of MMRR who may be adversely affected by the proposed abandonment will be adequately protected by the labor protective conditions in *Oregon*Short Line R Co -- Abandonment--Goshen. 360 I.C.C. 91 (1979).

CONCLUSION

Application of the regulatory requirements and procedures of 49 U.S.C. §§ 10903 and 10904 to the abandonment of the Line proposed by MMRR is not required to carry out the rail transportation policy set forth in 49 U.S.C. § 10101, as previously shown. Nor is Board regulation required to protect shippers from the abuse of market power. Moreover, this abandonment is of limited scope. Adoption of a procedural schedule is warranted in this proceeding

Accordingly, MMRR respectfully urges the Board to grant an exemption for the proposed abandonment of the Line and from the OFA Provisions, and establish the proposed procedural schedule.

Scott G. Williams, Esq.

Senior Vice President and General Counsel-

RailAmerica, Inc.

5300 Broken Sound Boulevard N.W.

Second Floor

Boca Raton, FL 33487

(561) 226-1757

Laurs E. Gitomer, Esq

Law Offices of Louis E. Gitomer

600 Baltimore Avenue

Suite 301

Towson, MD 21204

(202) 466-6532

Attorneys for: MID-MICHIGAN RAILROAD, INC.

Dated: February 20, 2008

¹⁴ Michigan Central Railway, LLC-Acquisition and Operation Exemption-Lines of Norfolk Southern Railway Company, STB Finance Docket No. 35063 (STB served August 2, 2007).

EXHIBIT A-MAP




EXHIBIT B-COMBINED ENVIRONMENTAL AND HISTORIC REPORT

CERTIFICATE OF SERVICE OF COMBINED ENVIRONMENTAL AND HISTORIC REPORT

Pursuant to the requirements of 49 C.F.R. §1105.7(c) and .8(c), the undersigned hereby certifies that a copy of the Combined Environmental and Historic Report in Docket No. AB-364 (Sub-No. 14X) was mailed via first class mail on January 29, 2008, to the following parties:

Michigan Department of Environmental Quality Director, Mr. Steven Chester Constitution Hall Floor Number 6 525 West Allegan Street P.O. Box 30473 Lansing, MI 48909-7973

Honorable Daryl J. Delabbio County Administrator Kent County County Administration Building 300 Monroe Avenue, NW Grand Rapids, MI 49503-2206

Michigan Historic Center 702 West Kalamazoo Street P.O Box 30740 Lansing, MI 48909-8240

Michigan Department of Environmental Quality P.O. Box 30473-7973 Lansing, MI 48909

Detroit District Headquarters U S Army Corps of Engineers Detroit District 477 Michigan Ave Detroit, MI 48226

USDA Natural Resources Conservation Service 3001 Coolidge Street East Lansing, MI 48823-6350 U.S. Environmental Protection Agency Region 5 Metcalf Building Office of Strategic Environmental Analysis 77 West Jackson Boulevard Mailcode: B-19J Chicago, IL 60604

U.S. Fish and Wildlife Service Region 3 One Federal Drive BHW Federal Building Fort Snelling Twin Cities, MN 55111

National Oceanic and Atmospheric Administration National Geodetic Survey 1315 East-West Highway Silver Spring, MD 20910-3282

U.S. National Park Service Midwest Region 1709 Jackson Street Omaha, NE 68102

Mayor Jeanne Shores 301 East Main Street Lowell, MI 49331

Dr. Kenneth E. Snow Mayor, City of Greenville 411 South Lafayette Greenville, MI 48838

Honorable Chris Hyzer Administrator/Controller Montcalm County P.O. Box 368 Stanton, Michigan, 48888-0368 Mayor Shane T. Husted 120 S Pleasant St. Belding, MI 48809

Mr. James Banks Chairman Ionia County Board of Commissioners 602 Sixth Avenue Lake Odessa, MI 48849

> Louis E. Gitomer February 20, 2008

COMBINED ENVIRONMENTAL AND HISTORIC REPORT (49 C.F.R. 1105.7 and 1105.8)

Docket No. AB-364 (Sub-No. 14X)

MID-MICHIGAN RAILROAD, INC.-ABANDONMENT EXEMPTION-IN KENT, IONIA, AND MONTCALM COUNTIES, MI

Dated: January 29, 2008

ENVIRONMENTAL REPORT

(1) <u>Proposed Action and Alternatives</u>. Describe the proposed action, including commodities transported, the planned disposition (if any) of any rail line and other structures that may be involved, and any possible changes in current operations or maintenance practices. Also describe any reasonable alternatives to the proposed action. Include a readable, detailed map and drawings clearly delineating the project.

Mid-Michigan Railroad, Inc. ("MMRR") proposes to abandon the 24.7-mile rail line between Lowell, milepost 103.2, and Greenville, milepost 78 5, the end of the line, in Kent, Ionia, and Montcalm Counties, MI (the "Line"). Upon receipt of abandonment authority from the Surface Transportation Board (the "Board"), MMRR proposes to convert the Line to interim trail use/rail banking under 16 U.S.C. § 1247(d) through the sale of the Line to West Michigan Trails and Greenways Coalition ("WMTGC"). MMRR will salvage the track and materials from the Line, but will leave the ballast, ties, bridges and culverts in place for the use of the trail.

Abandonment of the Line will result in the removal of the rail. MMRR does not intend to disturb any sub grade or sub grade structures and does not intend to remove any bridge structures. The operations and maintenance of the line will cease. Removal of the Line will result in the elimination of 39 public road crossings and 42 private crossings.

In 2006 there were two shippers using the Line, Frigidaire Corporation ("Frigidaire") and Crop Production Services ("CPS"). Both were located in Greenville, MI, the end of the Line. Frigidaire closed its facility in Greenville, moved to Mexico and South Carolina and stopped

shipping in March 2006. CPS shipped one carload of fertilizer in December 2006. There have been no shipments over the Line in 2007 or 2008.

There are two alternatives to a full abandonment. One alternative would be for MMRR not to abandon the Line. No service has been provided on the Line since December 2006. The Line is a stub end track and therefore has no overhead traffic. With little, if any, potential traffic, MMRR has decided to seek abandonment of the Line. The other more likely alternative will be for MMRR to convert the Line to interim trail use/rail banking through the sale to WMTGC. MMRR has entered a Memorandum of Understanding with WMTGC. It would be MMRR's preference to obtain authority to abandon the Line and convert it to interim trail use/rail banking through the sale to WMTGC.

MMRR previously served on the required parties on October 22, 2007, and filed with the Board on November 27, 2007, a Combined Environmental and Historic Report (the "CEHR") for the Line in *Mid-Michigan Railroad, Inc.—Abandonment Exemption—in Kent and Montcalm Counties, MI*, STB Docket No. AB-364 (Sub-No 11X). The Board rejected the Petition for Exemption on procedural grounds without prejudice to refilling in a decision served on January 25, 2008. By this CEHR, MMRR is re-commencing the abandonment process for the Line.

Color copies of Exhibit 3-USGS Maps and Exhibit 4-Bridges and Structures in the Historic Report ("HR") are being served only on the Michigan Historic Center, since they are only required in the HR. Black and white copies of these documents are being served in the other copies of this CEHR, but MMRR will provide color copies of Exhibits 3 and 4 upon request.

A map of the proposed abandonment is attached hereto as Exhibit 1.1

(2) <u>Transportation System</u>. Describe the effects of the proposed action on regional or local transportation systems and patterns. Estimate the amount of traffic (passenger or freight) that will be diverted to other transportation systems or modes as a result of the proposed action.

No passenger traffic will be diverted to other modes as a result of the proposed abandonment. CPS, the only shipper on the line, has not used the Line since December 2006, when it received one carload. No traffic moved over the Line in 2007 or to date in 2008. Hence, at most the freight traffic from one rail car per year will be diverted to motor carrier.

Accordingly, the proposed abandonment should have no adverse effects on regional or local transportation systems and patterns.

- (3) <u>Land Use</u>. (i) Based on consultation with local and/or regional planning agencies and/or a review of the official planning documents prepared by such agencies, state whether the proposed action is consistent with existing land use plans. Describe any inconsistencies. (ii) Based on consultation with the U.S. Soil Conversation Service, state the effect of the proposed action on any prime agricultural land. (iii) If the action affects land or water uses within a designated coastal zone, include the coastal zone information required by 1105.9. (iv) If the proposed action is an abandonment, state whether or not the right-of-way is suitable for alternative public use under 49 U.S.C. § 10905 and explain why.
- (i) MMRR considers the proposed abandonment to be consistent with existing land use plans. Other than in Lowell and Greenville, the land adjoining the Line is mainly rural in character.

MMRR contacted Kent, Ionia, and Montcalm Counties, MI and the cities of Lowell, Belding and Greenville, MI by letters dated January 29, 2008. See Exhibit 2. No response has been received as of this date. A copy of this Environmental Report has been mailed to the appropriate local and state agencies for their information and further comment.

¹ The copy of the map that accompanied the information-gathering letter has been removed from that letter. That map was the same as the map in Exhibit 1 accompanying this report.

- (ii) MMRR does not believe that there is any prime agricultural land that will be affected MMRR notified the United States Department of Agriculture ("USDA") Natural Resources Conservation Service (the agency succeeding to the responsibilities of the Soil Conservation Service) of the proposed abandonment by letter dated January 29, 2008, and requested assistance in identifying any potential effects on prime agricultural land. See Exhibit 2. A response to the prior CEHR stating that "[a]bandonment of the rail line will not result in the conversion of prime and unique farmland" is attached in Exhibit 5.
 - (iii) The Line does not pass through a designated coastal zone.
- (iv) Based on discussions with WMTGC, MMRR believes that the Line is suitable for interim trail use/ rail banking.
- (4) Energy. (i) Describe the effect of the proposed action on transportation of energy resources. (ii) Describe the effect of the proposed action on recyclable commodities. (iii) State whether the proposed action will result in an increase or decrease in overall energy efficiency and explain why. (iv) If the proposed action will cause diversions from rail to motor carriage of more than: (A) 1,000 rail carloads a year; or (B) an average of 50 rail carloads per mile per year for any part of the affected line, quantify the resulting net change in energy consumption and show the data and methodology used to arrive at the figure given.
- (i) The proposed abandonment will have no effect on the transportation of energy resources.
- (ii) The proposed abandonment will have no effect on the transportation of recyclable commodities.
- (iii) The proposed abandonment will have minimal effect on overall energy efficiency since there has been no traffic on the Line since December 2006
- (iv) The proposed abandonment will not cause the diversion more than 1,000 rail carloads a year; or an average of 50 rail carloads per mile per year for any part of the Line of rail traffic to motor carriage.

- (5) Air. (i) If the proposed action will result in either: (A) An increase in rail traffic of at least 100 percent (measured in gross ton miles annually) or an increase of at least eight trains a day on any segment of rail line affected by the proposal, or (B) an increase in rail yard activity of at lease 100 percent (measured by carload activity), or (C) an average increase in truck traffic of more than 10 percent of the average daily traffic or 50 vehicles a day on any affected road segment, quantify the anticipated effect on air emissions. For a proposal under 49 U.S.C. § 10901 (or § 10505) to construct a new line or reinstitute service over a previously abandoned line, only the eight train a day provision in sub-section (5)(i)(A) will apply. (ii) If the proposed action affects a class I or nonattainment area under the Clean Air Act, and will result in either: (A) an increase in rail traffic of at least 50 percent (measured in gross ton miles annually) or an increase of at least three trains a day on any segment of rail line; (B) an increase in rail yard activity of at least 20 percent (measured by carload activity); or (C) an average increase in truck traffic of more than 10 percent of the average daily traffic or 50 vehicles a day on a given road segment, then state whether any expected increased emissions are within the parameters established by the State Implementation Plan. However, for a rail construction under 49 U.S.C. § 10901 (or 49 U.S.C. § 10505), or a case involving the reinstitution of service over a previously abandoned line, only the three train a day threshold in this item shall apply. (iii) If transportation of ozone depleting materials (such as nitrogen oxide and freon) is contemplated, identify: the materials and quantity: the frequency of service; safety practices (including any speed restrictions); the applicant's safety record (to the extent available) on derailments, accidents and spills; contingency plans to deal with accidental spills; and the likelihood of an accidental release of ozone depleting materials in the event of a collision or derailment.
- (i) The proposed abandonment will not result in meeting or exceeding the specified thresholds.
- (ii) The proposed abandonment will not result in meeting or exceeding the specified thresholds.
- (iii) The proposed abandonment will not affect the transportation of ozone depleting materials.
- (6) Noise. If any of the thresholds identified in item (5)(i) of this section are surpassed, state whether the proposed action will cause: (i) an incremental increase in noise levels of three decibels Ldn or more: or (ii) an increase to a noise level of 65 decibels Ldn or greater. If so, identify sensitive receptors (e.g., schools, libraries, hospitals, residences, retirement communities, and nursing homes) in the project area, and quantify the noise increase for these receptors if the thresholds are surpassed.

Not applicable.

(7) <u>Safety</u>. (i) Describe any effects of the proposed action on public health and safety (including vehicle delay time at railroad grade crossings). (ii) If hazardous materials are

expected to be transported, identify: the materials and quantity; the frequency of service; whether chemicals are being transported that, if mixed, could react to form more hazardous compounds; safety practices (including any speed restrictions); the applicant's safety record (to the extent available) on derailments, accidents and hazardous spills; the contingency plans to deal with accidental spills; and the likelihood of an accidental release of hazardous materials. (iii) If there are any known hazardous waste sites or sites where there have been known hazardous materials spills on the right-of-way, identify the location of those sites and the types of hazardous materials involved.

- (i) The proposed abandonment will have no detrimental effects on public health and safety. MMRR will cease operating over the Line. As a result of the abandonment, MMRR will remove 39 public road crossings and 42 private crossings.
 - (ii) The proposed abandonment will not affect the transportation of hazardous materials.
- (iii) There was a spill of liquid nitrogen fertilizer, a non-hazardous material, at a siding at milepost 95.9 in December 2001. There was a loss of about 13,000 to 14,000 gallons. As a result of the spill, under the direction of the Michigan Department of Agriculture ("MDAG"), about eight barrels were loaded with the spilled liquid nitrogen fertilizer that had pooled on the ground, and about 10 to 12 inches of soil were removed down to the clay along 360 feet, resulting in the removal of about 65 to 70 cubic yards of soil. The soil was secured at another location to be used as fertilizer in the spring and the drums of the liquid nitrogen fertilizer were moved to the shipper's storage facility. MDAG approved back filling the excavation with sand, which was done. The spill had apparently occurred on December 2, 2001 and MMRR was notified on December 3, 2001. The removal of the soil and clean-up of the spill was completed on December 4, 2001.

MMRR is not aware of any known hazardous waste sites or sites where there have been known hazardous materials spills on the Line.

(8) <u>Biological Resources</u>. (i) Based on consultation with the U.S. Fish and Wildlife Service, state whether the proposed action is likely to adversely affect endangered or threatened species or areas designated as a critical habitat, and if so, describe the effects. (ii) State whether

wildlife sanctuaries or refuges, National or State parks or forests will be affected, and describe any effects.

- (i) MMRR does not believe that the proposed action is likely to adversely affect endangered or threatened species or areas designated as a critical habitat. MMRR notified the U.S. Fish and Wildlife Service ("USF&W") of the proposed abandonment by letter dated January 29, 2008, and requested assistance in determining whether the proposed abandonment will adversely affect endangered or threatened species or areas designated as a critical habitat. See Exhibit 2. A copy of this Report was supplied to the USF&W for its information and further comment. By letter dated October 26, 2007, in response to the prior CEHR, USF&W indicated that it "does not have any concerns regarding real estate matters in the abandonments." A copy of the letter is in Exhibit 5.
- (ii) Between Belding and Greenville, the Line passes through the Flat River State Game Area. MMRR does not expect the abandonment to affect the Flat River State Game Area since MMRR is planning to cease operations, only remove track and materials, and convert the Line to interim trail use/rail banking.

MMRR is unaware of any other wildlife sanctuaries or refuges, National or State parks or forests that would be adversely affected by the proposed abandonment.

MMRR notified the National Parks Service of the proposed abandonment by letter dated January 29, 2008, and requested assistance in identifying any potential effects on wildlife sanctuaries or refuges, National or State parks or forests. See Exhibit 2. To date, no response to this request has been received. A copy of this Report is being supplied to the National Park Service for its information and comment.

(9) <u>Water</u>. (i) Based on consultation with State water quality officials, state whether the proposed action is consistent with applicable Federal, State or local water quality standards. Describe any inconsistencies. (ii) Based on consultation with the U.S. Army Corps of Engineers,

state whether permits under section 404 of the Clean Water Act (33 U.S.C. § 1344) are required for the proposed action and whether any designated wetlands or 100-year flood plains will be affected. Describe the effects. (iii) State whether permits under section 402 of the Clean Water Act (33 U.S.C. § 1342) are required for the proposed action.

- (i) MMRR is confident that the proposed abandonment will be consistent with applicable water quality standards. MMRR contacted the Michigan Department of Environmental Quality ("MIDEQ") and the United States Environmental Protection Agency ("USEPA") by letters dated January 29, 2008. See Exhibit 2. To date, no response to this request has been received. A copy of this Report has been supplied to the MIDEQ and USEPA for their information and comment.
- (ii) MMRR believes that no permits under section 404 of the Clean Water Act are required for the proposed abandonment and that no designated wetlands or 100-year flood plains will be affected by the proposed abandonment. MMRR does not plan to salvage any of the crossties, ballast, or bridges on the Line so that they can be used when the Line is converted to interim trail use/rail banking. Upon receiving abandonment authority, removal of material will be accomplished by use of the right-of-way for access, along with existing public and private crossings. No new access roads are contemplated. MMRR does not intend to disturb any of the underlying roadbed or perform any activities that would cause sedimentation or erosion of the soil, and does not anticipate any dredging or use of fill in the removal of the track material. Debris will be transported away from the Line and will not be discarded along the right-of-way nor be placed or left in streams or wetlands, or along the banks of such waterways. Also, during track removal, appropriate measures will be implemented to prevent or control spills from fuels, lubricants or any other pollutant materials from entering any waterways. Based upon this course of action, MMRR does not believe a permit under Section 404 of the Clean Water Act will be required.

MMRR contacted the U.S. Army Corps of Engineers by letter dated January 29, 2008 and has received no response to date. *See* Exhibit 2. A copy of this Report has been supplied to the U.S. Army Corps of Engineers for its information and comment.

- (iii) MMRR believes that no permit under section 402 of the Clean Water Act would be required for the abandonment. MMRR does not plan to salvage any of the ties, ballast, or bridges on the Line so that they can be used when the Line is converted to interim trail use/rail banking. MMRR contacted the MIDEQ and the USEPA by letter dated January 29, 2008. See Exhibit 2. A copy of this Report has been supplied to the MIDEQ and USEPA for their information and further comment.
- (10) <u>Proposed Mitigation</u>. Describe any actions that are proposed to mitigate adverse environmental impacts, indicating why the proposed mitigation is appropriate.

MMRR does not expect any adverse environmental impact from the proposed abandonment and, therefore, see no need for any mitigating actions. MMRR will, of course, adhere to any remedial actions suggested by the recipients of this Report, which are required by the Board.

HISTORIC REPORT

- 1. A U.S.G.S. topographic map (or alternate map drawn to scale and sufficiently detailed to show buildings and other structures in the vicinity of the proposed action) showing the location of the proposed action, and the locations and approximate dimensions of railroad structures that are 50 years old or older and are part of the proposed action;
- U.S. Geological Survey Maps have been supplied to the Michigan Historic Center ("MIHC"). See Exhibit 3.
- 2. A written description of the right of way (including approximate widths, to the extent known), and the topography and urban and/or rural characteristics of the surrounding area;
- The 24.7-mile right-of-way is generally 100 feet wide, with some variance in towns and villages.

The Line begins in northwest Lowell at milepost 103.2 at an elevation of about 650 feet, just south of Foreman Street. The Line travels in a northerly direction, west of the Flat River.

After crossing 3 Mile Road NE, the Line turns in a northeasterly direction until its reaches 5 Mile Road NE where it runs parallel to that road for about 4,000 feet. The Line then turns northeast and passes to the southeast of Smyrna before it crosses Seely Creek just before the confluence with the Flat River.

The Line continues northeast, generally parallel to the Flat River until it crosses Michigan Highway 44 before crossing the Flat River and entering the town of Belding. The Line passes along the west and north of Belding before crossing the Flat River east of Michigan Highway 91. Passing through the portion of Belding north of the Flat River, the Line turns northeasterly and crosses the Flat River again before turning in a northerly direction near Long Lake Road.

The Line then travels in a north northwesterly direction to the east of the Flat River. The Line passes through the Flat River State Game Area and then enters the eastern section of Greenville. In a northerly direction, the Line crosses the Flat River two more times before turning northeasterly to the east of the Flat River. The Line then crosses Michigan Route 91 before terminating north of Churchill Lake at milepost 78.5.

3. Good quality photographs (actual photographic prints, not photocopies) of railroad structures on the property that are 50 years old or older and of the immediately surrounding area;

Photographs of the bridges on the Line and a detailed description of the bridges are attached as Exhibit 4 MMRR has entered a Memorandum of Understanding with WMTGC to convert the Line into interim trail use/rail banking. MMRR has agreed to leave the ties, ballast, and bridges intact for trail use. Therefore, MMRR will not be removing any of the bridges on the line. MMRR will only remove the track and materials (but not the ties) from the bridges, but will leave the bridges in place for trail use.

4. The date(s) of construction of the structure(s), and the date(s) and extent of any major alterations, to the extent such information is known;

See Exhibit 4.

5. A brief narrative history of carrier operations in the arca, and an explanation of what, if any, changes are contemplated as a result of the proposed action;

MMRR has operated over the Line between Lowell and Greenville since 1987 when it acquired the Line from CSX Transportation, Inc. The last shipper on the Line is located in Greenville. CPS was last served in December 2006. The proposed abandonment will not result in a change of operations since there has been no demand for rail service.

The Belding to Greenville portion of the Line was opened 1871 by the Detroit, Lansing & Lake Michigan Railroad Company (1871-1872). The Belding to Lowell segment was opened by Grand Rapids, Belding and Saginaw Railroad Company (1898-1903) 1899. Both eventually amalgamated into Pere Marquette Railroad Company ("Pere Marquette") in 1900. Pere Marquette was sold to the C&O Railway Company ("C&O") in 1947. As part of the Chessie System, the C&O was merged into CSX Transportation, Inc.

CSXT sold the Line to MMRR in 1987. At that time, MMRR was a subsidiary of RailTex, Inc. RailTex merged into RailAmerica, Inc. in 2000.

6 A brief summary of documents in the carrier's possession, such as engineering drawings, that might be useful in documenting a structure that is found to be historic;

MMRR possesses the valuation maps of the Line, but is not aware of any other documentation in its possession.

7. An opinion (based on readily available information in the railroad's possession) as to whether the site and/or structures meet the criteria for listing on the National Register of Historic Places (36 C.F.R. 60.4), and whether there is a likelihood of archeological resources or any other previously unknown historic properties in the project area, and the basis for these opinions (including any consultations with the State Historic Preservation Office, local historical societies or universities);

MMRR believes that the bridges and structures on the Line are not unusual or noteworthy

for inclusion on the National Register of Historic Places. It is also MMRR' opinion that there are no archeological resources or other railroad related historic properties in the project area.

Moreover, since MMRR is agreeable to converting the Line to interim trail use/rail banking,

MMRR does not plan to alter, remove or dispose of any of the bridges that are on the Line.

8. A description (based on readily available information in the railroad's possession) of any known prior subsurface ground disturbance or fill, environmental conditions (naturally occurring or manmade) that might affect the archeological recovery of resources (such as swampy conditions or the presence of toxic waste), and the surrounding terrain.

MMRR believes that there are no existing records as to the nature of any known subsurface ground disturbance or fill, or environmental conditions that might affect the archeological recovery of any potential resources.

9. Within 30 days of receipt of the historic report, the State Historic Preservation Officer may request the following additional information regarding specific non railroad owned properties or groups of properties immediately adjacent to the railroad right-of-way: photographs of specified properties that can be readily seen from the railroad right-of-way (or other public rights-of-way adjacent to the property) and a written description of any previously discovered archeological sites, identifying the location and type of the site (*i.e.* prehistoric or native American).

MMRR does not foresee the likelihood that any additional information will need to be supplied in association with the proposed abandonment other than that information previously submitted. But, if any additional information is requested, MMRR will promptly supply the necessary information.

MMRR contacted MIHC. See Exhibit 2. No response has been received. A copy of this Report has been mailed to MIHC.

EXHIBIT 1 – MAP




EXHIBIT 2 – LETTERS

LOUIS E. GITOMER
LOU_GITOMER@VERIZON,NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

National Oceanic and Atmospheric Administration National Geodetic Survey 1315 East-West Highway Silver Spring, MD 20910-3282

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc – Abandonment Exemption-in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Louis E. Gitomer

Sincerely wours

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

U.S. Fish and Wildlife Service, Region 3
One Federal Drive
BHW Federal Building
Fort Snelling
Twin Cities, MN 55111

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc.—
Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Louis E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

U.S. Environmental Protection Agency, Region 5
Metcalf Building
Office of Strategic Environmental Analysis
77 West Jackson Boulevard, Mailcode: B-19J
Chicago, IL 60604

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc –
Abandonment Exemption-in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Louis E. Gitomer

Sincerely yours.

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

USDA Natural Resources Conservation Service 3001 Coolidge Street East Lansing, MI 48823-6350

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc.—
Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Sincerely yours,

Louis E. Gitomer

Aftorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Detroit District Headquarters U.S. Army Corps of Engineers Detroit District 477 Michigan Ave. Detroit, MI 48226

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc – Abandonment Exemption-in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Sincerely yours,

odis E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Manager, Federal Project Review Michigan Department of Commerce Michigan Neighborhood Builders Alliance P.O. Box 30242 Lansing, MI 48909

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc – Abandonment Exemption-in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption sceking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Sincerely yours

ours E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Michigan Department of Environmental Quality P.O. Box 30473-7973 Lansing, MI 48909

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc.—
Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Louis E Citomer

Mitorney for Mid-Michigan Railroad, Inc.

Louis E Gitomer
Lou_Gitomer@verizon.net

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

I

Michigan Historic Center 702 West Kalamazoo Street P.O. Box 30740 Lansing, MI 48909-8240

> RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc.— Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Sincerely yours

Louis E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

Louis E. Gitomer
Lou_Gitomer@verizon.net

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

U.S. National Park Service Midwest Region 1709 Jackson Street Omaha, NE 68102

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc – Abandonment Exemption-in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

KHI NI

Louis E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Honorable Chris Hyzer Administrator/Controller Montcalm County P.O. Box 368 Stanton, Michigan, 48888-0368

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc. –
Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Mr. Hyzer:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

ous E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Mayor Jeanne Shores 301 East Main Street Lowell, MI 49331

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc.—
Abandonment Exemption-in Kent, Ionia, and Montcalm Counties, MI

Dear Mayor Shores:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Lowis E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUTTE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Dr. Kenneth E. Snow Mayor, City of Greenville 411 South Lafayette Greenville, MI 48838

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc – Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Mayor Snow:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Sincerely

ロカノが

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Honorable James Banks, Chairman Board of Commissioners Ionia County 602 Sixth Avenue Lake Odessa, MI 48849

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc.—
Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Chairman Banks:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.

Loais E. Gitomer

Sincerely your

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E. GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Mayor Shane T. Husted 120 S. Pleasant St. Belding, MI 48809

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc – Abandonment Exemption-in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).

Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer. 600 Baltimore Avenue. Suite 301, Towson, MD 21204.

ons E. Gitomer

Attorney for Mid-Michigan Railroad, Inc.

LOUIS E GITOMER
LOU_GITOMER@VERIZON.NET

January 29, 2008

THE ADAMS BUILDING, SUITE 301 600 BALTIMORE AVENUE TOWSON, MARYLAND 21204-4022 (202) 466-6532 FAX (410) 332-0885

Honorable Daryl J. Delabbio County Administrator, Kent County County Administration Building 300 Monroe Avenue, NW Grand Rapids, MI 49503-2206

RE: Docket No. AB-364 (Sub-No. 14X), Mid-Michigan Railroad, Inc.—
Abandonment Exemption—in Kent, Ionia, and Montcalm Counties, MI

Dear Madam/Sir:

On or about February 19, 2008, we expect to be filing with the Surface Transportation Board ("STB") a petition for exemption seeking authority for Mid-Michigan Railroad, Inc. ("MMRR") to abandon a 24.7-mile rail line between milepost 103.20, at Lowell, and milepost 78.50, at Greenville, the end of the line proposed for abandonment, in Kent, Ionia, and Montcalm Counties, MI.

Attached is a Combined Environmental and Historic Report describing the proposed action and any expected environmental and historic effects, as well as a map of the affected area. We are providing this report so that you may review the information that will form the basis for the STB's independent environmental analysis of this proceeding. If any of the information is misleading or incorrect, if you believe that pertinent information is missing, or if you have any questions about the STB's environmental review process, please contact the Section of Environmental Analysis (SEA), Surface Transportation Board, 395 E Street, SW, Washington, DC 20423, telephone 202-245-0295 and refer to the above Docket No. AB-364 (Sub-No. 14X).


Because the applicable statutes and regulations impose stringent deadlines for processing this action, your written comments to SEA (with a copy to our representative) would be appreciated within 3 weeks. Your comments will be considered by the STB in evaluating the environmental impacts of the contemplated action. If there are any questions concerning this proposal, please contact our representative directly. Our representative in this matter is Louis E. Gitomer who may be contacted by telephone at 410-296-2250, email at Lou_Gitomer@verizon.net, or mail at Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204.


Louis E. Gitomer


Sincerely yours


Attorney for Mid-Michigan Railroad, Inc.


EXHIBIT 3 – USGS MAPS

















EXHIBIT 4 – BRIDGE PHOTOGRAPHS AND DESCRIPTIONS

Greenville 81.10

		Reid	ge Inspect	ion Report			WAST 1
		Mid-Michigan R		оп пороте			
	₹ .	Greenville	Names				7
1 m 1 m		Michigan					
Inspected	Rv.	Stan Reimer					
Inspection		May 22, 2006			CAN	・	
	estle Struct		<u>-</u>				
			B-U4	0			
Structure	PT	Deck Typ.	Ballast	Crossing	River	3.5%	
# Spans	13	Length	175	Access:	< 1/2 mile		
# Tracks.	1	Height		Flow Dir.	R-L	Greenville 81.	10
Year Built	1943	Alignment	<u> </u>			Flat River	
	General		Supe	rstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Fair		Stringers	Poor	Bridge Seats/Caps	Bad
Cha	annel/Road			oor Beams		Abuts/Backwalls	Poor
	Approach			Truss/Slab		Piers, Towers, Bents	Poor
	Deck	G/F/P/ <u>B</u>		Top Flange		Misc	G/F/P/B
	Ties	Fair	Bot	tom Flange		Guard Rail	
Ţ	ie Spacers		Web	/Diagonals			
	Track	Fair	Beari	ng Stiffners			
	Footwalk			Bracing			
	Handrail			Bearings		Overall Rating:	Poor
		·	CO	MMENTS		· -	
Photo #	Remarks		<u> </u>				
	Delcan 200	06 Notes:		-			
P11-P12		cap crushing - u	rgent repla	ecement sti	II required		
P10		piles 2 and 6 pu					
		·					
	Delcan 200	05 Notes:					
P01	- Approac	hes low					·
P06-P09	- Bent 11	urgent pile cap	replaceme	ent from las	st year not	yet done - cap crushir	ıg
	- Bent 7 -	piles 2 and 3 pu	nky, plie 4	OK			
	- Bent 8 -	piles 2 and 6 pu	nky (piles 4	4 and 5 see	m to be Ol	<u> </u>	
	Delcan 200						
P01		hes uneven					
P03		eck ties OK					
P04		d under traffic -		<u>ıg evident</u> ı	near first a	pproach	
		pile 4 hollow, pil					
		<u>pile 2 hollow, pil</u>		- ——			
		piles 2, 4 and 5 a			ine		
		pile 6 punky nea					
		pile 4 is punky			<u> </u>		
P09		pile cap crushe		replaceme	nt required	<u> </u>	
P02	- Depris in	channel on rigi		0500			
<u> </u>	_		IENANCE	RECOMME	NDATIONS	<u> </u>	
	Description						
		le cap on bent 1					
		B - piies 2 and 6	- \$5,000				
5 years	Post bents		44 17				
	Randing b	rogram for bent	14 pile car	<u> </u>			

Greenville 81.60

		Brid	ge Inspect	ion Report		2 0	32.75	
	3	Mid-Michigan R				7 Salanain	4.0	
	S .	Greenville	-					
	,	Michigan				المراجعة المراجعة المراجعة المراجعة		
Inspected	By:	Stan Relmer		و وسيرها				
Inspection	Date:	May 22, 2006			CAN			
Steel Stru	cture (Gird	ers/Beams)						
Structure	DPG	Deck Typ	Open	Crossing	Stream			
# Spans	2	Length	100	Access	< 1/2 mile			
# Tracks	1	Height		Flow Dir	R-L	Greenville 81.	.60	
Year Built.	1910	Alignment	T			Stream		
	General	G/F/P/B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B	
	Scour	Fair		Stringers	<u> </u>	Bridge Seats/Caps	Fair	
Cha	annel/Road	Fair		oor Beams	Fair	Abuts/Backwalls	Poor	
	Approach	Fair	Girders	Truss/Slab	Fair	Piers, Towers, Bents	Poor	
	Deck	G/F/P/B		Top Flange	Fair	Misc	G/F/P/B	
Ties (C)pen Deck)	Fair	Bot	tom Flange	Fair	Guard Rail		
	ie Spacers	Fair	Web	/Diagonals	Fair			
	Track	<u>Fair</u>	Bean	ng Stiffners	Fair			
	Footwalk			Bracing	Fair			
	Handrail			Bearings	<u>Fair</u>	Overall Rating:	Fair	
			CO	MMENTS				
Photo #	Remarks							
	Delcan 200				· <u> </u>			
<u>P01</u>		roach a bit low		_	_			
P03		<u>ck - 12 reject tie</u>						
P09	<u>- Pier 1 - r</u>	ight side - moni	toring crac	king - OK f	or now	. —— ———		
i	Dal 000	of Net						
<u> </u>	Delcan 200 - Approac							
<u> </u>		ct ties (6%)	— —					
	Delcan 200				<u> </u>			
P01		hes a bit low			_			
P03		ct ties (5%)	·					
P12.P06		rack below right	t bearing o	n upmile fa	ice only - n	nonitor		
_ P08						ous repair - monitor		
	UMA 2003	Notes:						
						crete. Backwall is		
L				<u>ns. Pler 1 c</u>	oncrete is	scaling. Plan on conc	rete	
	repairs to	oler and abutme						
			ENANCE	RECOMME	NDATIONS	<u> </u>		
	Description							
Monitor	<u>Crack on u</u>	pmileage face o	T Pier 1					
 -		 -						
			-					
								
——— ·								
— — ·								

Greenville 87.40

Bridge Inspection Report							
		Mid-Michigan R		ion Kaport			1.
	₹	Greenville	ailway				
		Michigan					
Inspected	Rv:	Stan Reimer				10 1 <u>111 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-</u>	ATTEMENT
Inspection Date:		May 22, 2006		DEL	CAN		
		ture with Steel M	lainspan(s)			-
Structure	PT/DPG	Deck Typ	Open	Crossing:	River		
# Spans	7	Length	165	Access:	< 1/2 mile		
# Tracks	1 1	Height		Flow Dir		Greenville 87	'.4
Year Built	1914	Alignment	<u>T</u>			Flat River	
	General	G/F/P/B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Fair		Stringers	Poor	Bridge Seats/Caps	Fair
Ch	annel/Road	Fair		oor Beams		Abuts/Backwalls	Fair
	Approach	Fair	Girders/	Truss/Slab	Fair	Piers, Towers, Bents	Fair
	Deck	G/F/P/B		Top Flange	Fair	Misc	G/F/P/B
	Open Deck)	Poor	Bot	lom Flange	Fair	Guard Rail	
1	re Spacers	Fair	Web	/Diagonals	Fair		
	Track	Fair	Beari	ng Stiffners	Fair		
	Footwalk			Bracing	Fair		
	<u>Handrail</u>			Bearings	<u>Fair</u>	Overall Rating:	Fair
			CO	MMENTS_			
Photo #	Remarks						
	Delcan 200						
P12						stringers OK for now	
P05,P06		stringers 2 and					
<u>P0</u> 3 _	- Obeu de	ck on DPG main	<u>spans - 18</u>	reject ties	on mainsp	ans	
							
							
	Delcan 200)5 Notes:					
	- Approac						
		ect ties (18%)					
		stringers 2 and					
		Stringer 1 rotter	1				
	Delcan 200						
P01	- Approac						
P03		ect ties (17%)		 _			
P04 P12		eck ties on appr stringer 2 splitti					
	- Span I -			RECOMME	NDATIONS		
Urgenov	Description		ENANCE	VECANIME	ADV HOUS	<u> </u>	
Urgency 1 year			8 to 8 - CR	000			
. , yeur	Replace stringer 1 - bents 6 to 8 - \$6,000						
	 						
							
			-				
<u> </u>							

Greenville 88.20

v		Delai.		lan Banari		Maring Carlo	
		Bridge Inspection Report Mid-Michigan Railway				The state of the s	المارية
	3		kaliway			And the second	
	N ' '	Greenville	:				
	Des	Michigan					
Inspected		Stan Reimer		DELC	CAN		.]
Inspection		May 22, 2006					1000
		ers/Beams)		 1			
	teel Tresti		Ballast	Crossing	River	(4)(大学) \$1 在 10 10 10 10 10 10 10 10 10 10 10 10 10	BEST STATES
# Spans	17	Length	225	Access.	Road	0	
# Tracks	1 1	Height	<u> </u>	Flow Dir		Greenville 88.	20
Year Built	1918	Alignment				Flat River	C/E/D/D
	General	G/F/P/B	Supe	erstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Fair		Stringers	Good	Bridge Seats/Caps	Fair
Cha	annel/Road	Fair		loor Beams		Abuts/Backwalls	<u>Fair</u>
	Approach	Fair		/Truss/Slab		Piers, Towers, Bents	Fair
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B
	Open Deck)	Good		tom Flange		Guard Rail	
[_]	ie Spacers	Good		/Diagonals			
	Track	Good	Веал	ng Stiffners		<u> </u>	
	Footwalk			Bracing	Fair		
	Handrail			Bearings		Overall Rating:	Fair
			CO	MMENTS			
Photo #	Remarks			_		<u>. —————</u>	
	Delcan 200						
P01-P03		ge in condition :					
	- Since ma	ajor repairs were	relatively	recent, det	alled insp	ection of piles not yet i	rqd
							
							
							
	Delcan 200	Notes:					
		ges since 2004 i	nenection				
	Delcan 200		<u>napecuon</u>				
P01	- Approac						-
P06			ed on cut t	imber piles	- sili plate	s at varying elevations	
P05,P07		and 16 not repla					
P02		ck - all ties are n			ition		
	UMA 2003						1
						steel frame bents and	
		ers. New deck.	All fair. No	action req	uired		
		MAIN	TENANCE	RECOMME	NDATIONS	3	
Urgency	Descriptio	n					
	No action (
[_		_ _					4
ļ.———	 -			<u></u>			I

Greenville 89.30

hard dependent of the same		5.4			·- <u>-</u> -				
				ion Report					
 - - 	3	Mid-Michigan R	ailway						
	>	Greenville				213	<u> </u>		
٠ <u>٠٠ . ۲۰۰۰</u> .		Michigan	_						
Inspected	By:	Stan Reimer							
Inspection		May 22, 2006		DELC					
Timber Tre	estle Struct	ture with Steel M	ainspan(s	1		7-4	12 July 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Structure			Open	Crossing	River		The state of the		
# Spans	17	Length	277	Access	Road	- 17 TV 1	<u>`</u> i		
# Tracks	1	· ——	211	Flow Dir	R-L	Greenville 89.	20		
Year Built	7	Height	<u> —</u> т	FIOW DII	K-L	Flat River	.30		
rear built		Alignment			0:5:0		0.5.0		
	General		Supe	rstructure	G/F/P/B	Substructure	G/F/P/B 		
	Scour	Fair		Stringers	Poor	Bridge Seats/Caps	Poor		
Cha	annel/Road			oor Beams		Abuts/Backwalls	Fair		
	Approach	Fair	Girders	Truss/Slab		Piers, Towers, Bents	Poor		
	Deck	 G/F/P/B	-	Top Flange		Misc	G/F/P/B		
Ties (C	pen Deck)	Fair		tom Flange		Guard Rail			
	ie Spacers	Fair		/Diagonals					
	Track	Fair		ng Stiffners					
<u> </u>	Footwalk	'		Bracing					
	Handrail					Overall Rating:	Poor		
	Handiali	<u> </u>		Bearings		Overall Kathiy.	POOL		
			ÇÜ	MMENTS					
Photo #	Remarks								
	Delcan 200								
P08		inkhole in ballas							
P06		1 in span 1 - rec							
P11,P12			s 12 and 1	3 are on co	ncrete sia	bs so not as urgent			
	Deican 200	35 Notes:							
P02		ap replaced							
P03		stringer 1 replace							
P12	- Stringer	1 crushing over	bent 16 (n	ot bent 18)					
	Delcan 200								
P01	- Approac	hes a bit low							
P03	- 0/28 reje	ct ties (0%) for b	eam span						
P22,P23		eck ties poor				<u> </u>			
P04	- Sinkhole	through ballast	trough flo	or near ber	it 2				
P05,P06		stringer 1 crush				to be replaced			
P09,P10		ile cap crushing							
P11						debris in river on right	<u> </u>		
P12		2 from bents 3 to							
P13		timber blocking			ottina				
P14									
P15		- Bent 13 - timber sill plate rotten and to be replaced - Bent 14 - timber sill plate rotten and to be replaced							
P16,P17		pile cap starting				low			
<u> </u>				RECOMME					
I lanca es	Donosinál s		FIVE			<u></u>			
	Description		-1 40 PF 1	100					
		ringer 1 over be				<u> </u>			
3 years		Il plates for bent							
3 years	Kebrace bi	le caps for bent	3 1, 14 and	15 - \$15,00	<u> </u>				

Greenville 89.31

1 14 men		Brid		-0-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	<u> </u>		
	3	Mid-Michigan R					
	3	Greenville	allway		546		
	7 ~	Michigan					
Inspected	Du-	Stan Reimer					
Inspected		May 22, 2006		DELC	SAN	.	
	ay Structu						
Structure.		Deck Typ		Crossing	Hwy		
# Spans	0	Length	0	Access	Road		
# Tracks	1	Height.		Flow Dir		Greenville 89	
Year Built	7	Alignment	<u>T</u>			Hwy. M-44 O/H	
	General	G/F/P/B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Fair_		Stringers		Bridge Seats/Caps	
Cha	annel/Road	Good		oor Beams		Abuts/Backwalls	
	Approach	Fair		Truss/Slab	Good	Piers, Towers, Bents	Good
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B
Ties (C)pen Deck)		Bot	tom Flange		Guard Rail	
	ie Spacers			/Diagonals			
	Track		Beari	ng Stiffners			
	Footwalk	Good		Bracing	_		
	Handrail			Веаппдз		Overall Rating:	Falr
			CO	MMENTS			
Photo #	Remarks						
	Delcan 200	Of Notes:		 -			
		ge in condition s	lnce 2005				
├ ──	- 100 011011	go in comandion a	,,,, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>		_		 f
	 -			_			
					-		
						<u> </u>	
- 							
							
	Delcan 200)5 Notes:					
		ge in condition s	ince 2004				
	Delcan 200		-				
P01		deck on steel g	irders				
	UMA 2003						
	- Not insp						
			TENANCE	RECOMME	NDATIONS	3	
Urgency	Descriptio						
	_ <u> </u>	· -		-			
					_		
— — 					_		
							
					<u> </u>		
							
 							
					_		

Greenville 91.60

						No. 100 Promise to the second	
				ion Report		A 1872	
	3	Mid-Michigan R	tailway			A Committee of the Comm	
	3	Greenville					1
	<u></u>	Michigan					
Inspected		Stan Reimer		DELC			
Inspection	Inspection Date: May 22, 20						3.27.45
Timber Tro	estle Struct	ure					
Structure	PΤ	Deck Typ	Deck Typ Ballast Crossing. Stream				X 100
# Spans	-6	Length	82	Access'	Road		
# Tracks	1	Height	_	Flow Dir	R-L	Greenville 91.	60
Year Built	?	Alignment				Stream	
	General	 G/F/P/B	Supe	erstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Fair		Stringers	Fair	Bridge Seats/Caps	Роог
Cha	annel/Road	Fair	F	loor Beams		Abuts/Backwalls	Fair
· ·	Approach	Fair	Girders	/Truss/Slab		Piers, Towers, Bents	Bad
	Deck	G/F/P/B		Top Flange	<u></u> -	Misc	G/F/P/B
	Ties	Fair		tom Flange		Guard Rail	
1 1	Tie Spacers			/Diagonals			-
_	Track	Fair		ng Stiffners			
	Footwalk			Bracing	Fair		
	Handrail			Bearings		Overall Rating:	Fair
			CO	MMENTS			
Photo #	Remarks						
1 11010 11	Delcan 200	06 Notes:			_		
		ge has urgent w	ork that ha	s not been	done		
P04		stumps 1 and 6					
P05				iles 1, 5 and	i 6 are rot	ten - urgent repair rqd	
P08		piles 1, 2, 3 and					
P09,P10	- Bent 7 p	le cap is rotten	on left				
	Delcan 200						
P03		stump 4 is rotte					
P04		piles 1, 2, 5 and					
P07		plle 1 is gone, p	les 2, 3 an	d 4 are pun	ky		
P09-P10		pile cap rotten					
	Delcan 200						
<u>P01</u>	- Approac						
- -<u></u> 		eck ties OK				-	
P06		piles 1, 2 and 5		piles 3 and	4 are pos	ited	
P07		Pile 4 completel					
P08,P10		pile 3 is rotten n				Maria di secono	4
P11		olle 1 is crushed					
P16,P18		pile cap split and		iaea, post 1	spiit and	ro na Daugag	<u>_</u>
P1 <u>6</u>	- Dent / -	pile cap is split		RECOMME	VDATION		
Hanamari	Dec!		CHANCE	VEA NIME	ADM HOW		
	Description		00.000				
		ts 2, 4 and 5 - \$3		10.000			
		<u>3 - pile 4, bent 4</u> ent 7 pil e cap - \$		10,000			—— - [
1 year		rogram - Bent 6		noet 1			
					_		——
Consider replacement with culvert for \$35,000							

Greenville 91.70

	_ i		ge Inspect			gristeria (s.	
一之	~	Mid-Michigan F	Railway				
	S	Greenville					
Inspected	Pu-	Michigan Stan Reimer	 ,			The second second	
Inspected		May 22, 2006		DELC	SAN		
Culvert		,,					
	' x 12' RC	Deck Typ		Crossing	Stream		
# Spans	1	Length [*]	13	Access:	Road	The second secon	7.00
# Tracks	1	Height		Flow Dir	R-L	Greenville 91.	70
Year Built	?	Alignment	T			Culvert	
	General	G/F/P/B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Fair		Stringers		Bridge Seats/Caps	_
Ch:	annel/Road	Fair		oor Beams		Abuts/Backwalls	Fair
	Approach	Fair		Truss/Slab	Fair	Piers, Towers, Bents	
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B
	Dpen Deck)			tom Flange		Guard Rail	
	ie Spacers			/Diagonals			
	Track Footwalk	Fair	Bearii	ng Stiffners Bracing			. —
	Handrail	·		Bearings		Overall Rating:	Fair
	naridiali		CO	MMENTS		Overall Nathing.	Fall
Photo #	Remarks			HINEITIS			
FIIOLO #	Delcan 200	16 Notes					
P01-P04		ge in condition	since 2005		- -		
					. — —		
							-
	Delcan 200)5 Notes:					_
	- No chan	ge in condition	since 2004				-
	Delcan 200						
P01	- Approac	hes OK					
P06	- <u>Good co</u> UMA 2003	ndition but over	grown	-			
	- Not insp						
	- NOL IIISPI		TENANCE	RECOMME	NDATIONS		
Urgency	Description						
Olgonoy	No action						
		·	-				
	<u> </u>						
							
	<u> </u>						

Greenville 94.70

، سسبب پنه خر وا		Brid	ge Inspect	ion Report			-
) 2		Mid-Michigan F	lailway	· · · · · · · · · · · · · · · · · · ·		mark .	<u> </u>
	$\mathbf{\tilde{s}}$	Greenville					
	<u></u>	Michigan					
Inspected		Stan Reimer			SAN		
Inspection		May 22, 2006				多是是特别的 。	
		ers/Beams)					
	on Bridge			Crossing	Stream		
# Spans		Length	0	Access	Road		
# Tracks	1	Height		Flow Dir		Greenville 94	
Year Built	7	Alignment	T		s. *	Road Bridg	
	General	_G/F/P/B_	Supe	rstructure	G/F/P/B	Substructure	<u>G/F/P/B</u>
	Scour		<u>-</u> .	Stringers		Bridge Seats/Caps	
Cha	annel/Road			oor Beams		Abuts/Backwalls	
=	Approach			Truss/Slab		Piers, Towers, Bents	
	Deck	G/F/P/B!		Top Flange		Misc	G/F/P/B
	Den Deck)			om Flange		Guard Rail	
<u> </u>	ie Spacers			/Diagonals			
	Track Footwalk	——————————————————————————————————————	Beani	ng Stiffners Bracing		<u> </u>	
				 =		Overall Betimes	Poor
	Handrail	<u>l</u>	00	Bearings		Overall Rating:	Poor
D #	D	·	- 60	MMENTS			
Photo #	Remarks Deican 200	No Marian					
P03		earing blocks for	or roll etrin	gere are ro	ting at an	de - OK for now	
PU3	- I IIIIDei R	earing blocks it	or rau sum	yer <u>s are ro</u>	ung at en	us - OK IOI IIOW	
_		- 					
						<u> </u>	
	Delcan 200						
		ge in condition :	since 2004				
	Delcan 200						
P01		road bridge adj					
P04		ucture is steel r					
<u> </u>		closing this br					
P01		e, consider rep posted for 15 to		a Cuivert W	iieii oriag	<u>a aranın ro ianı</u>	
	UMA 2003		0(19				
	- Not insp			. ———		-	
			TENANCE	RECOMME	NDATIONS	3	
Urgency	Description						
	No action						
					<u> </u>		
	<u> </u>	_ 	<u> </u>				
	<u> </u>						

Greenville 95.50

	Bridge Inspection Report								
	2	Mid-Michigan F		ion report					
	3	Greenville					1-2-2		
		Michigan							
Inspected	Dv.	Stan Reimer							
Inspection		May 22, 2006		DEL	CAN				
Timber Trestle Structure Structure PT D			Ballast Crossing Stream			11/1/19			
# Spans		Deck Typ: Length	13	Crossing Access	Stream < 1/2 mile		en 19		
# Tracks	 ;	Height.		Flow Dir	R-L	Greenville 95	50		
Year Built	1929	Alignment	Ť	FIOW DII	K.L	Cattle Pass			
rear built	General		<u>_</u>	rstructure	G/F/P/B	Substructure	G/F/P/B		
			- Supe						
Ch.	Scour	<u>Fair</u> Fair		Stringers oor Beams	Poor	Bridge Seats/Caps Abuts/Backwalls	Fair Fair		
Cna	annel/Road	Fair		Truss/Slab		Piers, Towers, Bents	Poor		
	Approach						-		
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B		
<u> </u>	Ties	Fair		tom Flange	L ———	Guard Rail			
	<u>ie Spacers</u>			/Diagonals		_ _			
I— —	Track	Fair	Bean	ng Stiffners		- ———			
	Footwalk			Bracing					
	Handrail			Bearings		Overall Rating:	Poor		
<u></u>			<u></u>	MMENTS					
Photo #	Remarks								
	Delcan 200								
P05		5 rotten at bent				· ——-			
P06		ap rotten on left		0.10		· ———			
		iles 2 and 4 are	roπen, pue	3 IS poste	<u> </u>				
P08	Delcan 200 - Stringer		-			<u> </u>			
P03-P04		ile cap rotten				·			
P05		piles 2 and 4 are	hollow						
F00.	Delcan 200		HOIION						
P01	- Approac								
P03		eck ties OK							
P06		piles 2 and 4 ho	llow						
P04,P07		p starting to ro			· · · · · · · · · · · · · · · · · · ·				
	UMA 2003				-				
			frame bei	nt. Bent 1 c	ap 1 is rott	ed on left side. 9-8x16			
						nt 1 needs to be			
		hin 3 years.							
		MAIN	TENANCE	RECOMME	NDATIONS				
Urgency	Description	n							
3 years		t 1 - \$10,000							
5 years	Replace Stringers \$10,000								
									

<u></u>		Brld	ge inspect	on Report			
	3	Mid-Michigan R					
	>	Greenville	•				深急,源
		Michigan					的以外
Inspected		Stan Reimer			SAN		
Inspection	Date:	May 22, 2006					
Culvert						Fill was Signer	14 A
	6' x 8' RCE	ا كليا الساحية عن الساحية	_	Crossing	Stream	Paris - Carrier	
# Spans	00	Length	0	Access	< 1/2 mile		
# Tracks	1	Height		Flow Dir	R-L	Greenville 98.	.00
Year Built	7	Alignment	С			Culvert	~~~
	General		Supe	rstructure	G/F/P/B_	Substructure	G/F/P/B
	Scour	Fair		Stringers		Bridge Seats/Caps	
Cha	annel/Road	Fair		oor Beams		Abuts/Backwalls	Fair
	Approach	Fair		Truss/Slab	Fair	Piers, Towers, Bents	أحسين
	Deck	G/F/P/B		Гор F <u>lange</u>		Misc	G/F/P/B
	Open Deck)			om Flange		Guard Rail	
<u> </u>	ie Spacers			/Diagonals			
	Track	Fair	<u>Beann</u>	ng Stiffners			
	Footwalk			Bracing			
	Handrail			Bearings		Overall Rating:	Fair
			CO	MMENTS			
Photo #	Remarks						
	Delcan 200						
P01-P04		ge in condition :	since 2005				
 	- Overgro	wn with brush_				_ ——	
_							
<u> </u>			···				
] ——							
] ——							
			-				
<u> </u>	Delcan 200)5 Notes:					
		ge in condition s	since 2004				
	Delcan 200	4 Notes:					
P01	- Approac	hes OK					
P02		alling in headwa	all of outlet	on left			
 _	UMA 2003						
	- Not Insp						
_			TENANCE	RECOMME	<u>NDATIONS</u>		
Urgency	Description						
	No action	necessary					
⊢							_
	<u> </u>						
├ ──┤				\-			
├── ┤	<u> </u>					 -	

			l	ion Dona-1			
1				ion Report			
		Mid-Michigan R	kaliway			建	
** TA 12.00	S	Greenville					
		Michigan		, 			18
Inspected		Stan Reimer		DEL	CAN		
Inspection		May 22, 2006					这是
	stle Struct					1946年	LEUKSEP :
Structure	PT	Deck Typ.	Ballast	Crossing	Stream	のでは、日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日	
# Spans	11	Length	13	Access	< 1/2 mile		
# Tracks	1 4000	Height.	_ 	Flow Dir	R-L	Greenville 99.	.50
Year Built	1929	Alignment				Cattle Pass	
	General	G/F/P/B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B
01	Scour	Fair	- 	Stringers	Fair	Bridge Seats/Caps	<u> Fair</u>
Cha	annel/Road	Fair Fair		loor Beams Truss/Slab		Abuts/Backwalls	Fair Poor
	Approach					Piers, Towers, Bents	
	Deck	G/F/P/B I		Top Flange		Misc	G/F/P/B
l <u>-</u>	Ties	Fair		tom Flange		Guard Rail	
<u> </u>	ie Spacers	 _		/Diagonals		L 	
	Track	<u>Fair</u>	Beari	ng Stiffners			
	Footwalk			Bracing			
	Handrail			Bearings		Overall Rating:	Fair
_			<u>co</u>	MMENTS			
Photo #	Remarks						
	Delcan 200						
P01-P05	- No chan	ge in condition :	since 2005				
[
							
<u> </u>		-					
——— —	Delcan 200	5 Notes					
		ge in condition s	ince 2004				
	Delcan 200						
P01	- Approac						
P03		eck ties OK			··		
P06		pile 3 split and t	o be bande	ed			
	UMA 2003	Notes:					
			le 1 needs	to be on pl	an to post.	Both caps are fair.	
	Ballast cur	bs are tipping.					
		MAIN'	TENANCE	RECOMME	NDATIONS		
	Descriptio						
	Banding p	rogram - bent 2,	pile 3				
├ ─						<u></u>	
							
 							

		D-1-1	ge Inenect	ion Report		3 9750 Sept - 1	F- 1, 71, 71, 11
	3			ion Kaport			
	>	Mid-Michigan R	kaliway			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	~	Greenville Michigan					
Inspected	Bv:	Stan Reimer					
Inspection		May 22, 2006		DEL(CAN		
	estle Struct						A TRACK
Structure	PT	Deck Typ.	Ballast	Crossing	Stream	学是这个人的	合并进行
# Spans	1	Length	13	Access	< 1/2 mile		
# Tracks	1	Height.		Flow Dir	R-L	Greenville 99	.60
Year Built	1929/50	Alignment				Cattle Pass	
	General	G/F/P/B	Supe	erstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Fair		Stringers	Poor	Bridge Seats/Caps	Fair
Cha	annel/Road	Fair	F	loor Beams		Abuts/Backwalls	Fair
	Approach	Fair	Girders	Truss/Slab		Piers, Towers, Bents	Bad
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B
	Ties	Fair	Bot	tom Flange		Guard Rail	
	ie Spacers			/Diagonals			
	Track	Fair	Bean	ng Stiffners			
	Footwalk			Bracing			
	Handrail			Веаппдѕ		Overall Rating:	Poor
			CO	MMENTS			
Photo #	Remarks		<u> </u>				_
	Delcan 200						
P04,P06						stringers are OK	
P05	- Bent 1 -	piles 1, 2, 4 and	5 are hollo	w and/or re	otten - nee	ds framing	
		 					
705 700	Delcan 200						
P05,P06		1 and 9 are rotte					
P04	- Bent 2 - Delcan 200	piles 1, 2, 4 and	5 are nonc	<u> </u>			
P01	- Approac		—— -				-
P02		leck ties OK				_ 	
P04		pile 5 hollow				 _	
P05		pile 4 punky					
P06,P07		s discolored, str	inger 9 sta	rting to rot			
	UMA 2003						
			nt 2 pile 1	s bad; 2, 4	& 5 are ho	llow; 3 is fair; 6 is soli	d
		is hollow. Bent	2 needs to	be framed	within 1 ye	ar.	
		MAIN	TENANCE	RECOMME	NDATIONS	3	
Urgency	Descriptio	n					
		t 2 - \$10,000					
3 years	Replace 2	stringers - \$10,0	000				
		 -					
							
I——						_ _	
_							
 					_	- 	
_							

- 22		Brid	ge inspect	ion Report	-	1	
2	3	Mid-Michigan R	7 -		, <u> </u>	September 1	S. Mark of S.
		Greenville					
		Michigan_					
Inspected	By:	Stan Reimer			SAN		
Inspection	Date:	May 22, 2006		JELL			
Cuivert							
Structure	CMP	Deck Typ	-	Crossing	Stream		<u> </u>
# Spans	o	Length	0	Access	Road		
# Tracks	1	Height		Flow Dir	R-L	Greenville 99	1.85
Year Built	3	Alignment	T			Culvert	
	General		Supe	rstructure	_G/F/P/B_	Substructure	_
	Scour	<u>Fair</u>		Stringers		Bridge Seats/Caps	
Cha	annel/Road	Fair		oor Beams	P-1-	Abuts/Backwalls	
	Approach	Fair		Truss/Slab	Fair	Piers, Towers, Bents	
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B
	Open Deck)			om Flange		Guard Rail	<u> </u>
Į.	le Spacers	<u> </u>		/Diagonals		<u> </u>	
-	Track Footwalk	Fair	Bean	ng Stiffners Bracing			
<u> </u>	Handrail					Overall Rating:	Fair
	Handraii			Bearings MMENTS		Overall Rating:	<u> Fair</u>
Dhata #	Remarks			MINIEN 13			
Photo #	Delcan 200	76 Notoe:	 				
		ge in condition (eince 2005			·	
	- NO CHAIL	ge in condition i	<u> </u>				
				_			
	_				_		
					•		
							
	Delcan 200	ge in condition :	-lane 2004				
	- No слап Deican 200		since zuu4				
P01	- Approac						
	- Pipe culv						
	UMA 2003						
	- Not insp	ected					
		MAIN	TENANCE	RECOMME	NDATIONS	S	
Urgency	Descriptio	n					
	No action	necessary					
		·					
_ —	_			<u>-</u>			
							
							

		Bride	ne inspect	ion Report			
ر دی ا	~	Mid-Michigan R		ion Report	_	· .	
	₹	Greenville	anway				ا نام م
		Michigan				The state of the s	
Inspected	Rv.	Stan Reimer					7 7
Inspection		May 22, 2006			CAN		~ jj
Culvert	Dato.	May 22, 2000					
Structure	CMP	Deck Typ		Crossing.	Stream		W. Warren
# Spans	- CINIP	Length	_ _	Access	Road		
# Tracks	<u> </u>	Height	` _	Flow Dir	R-L	Greenville 99	90
Year Built	1 7	Alignment	<u> </u>	1 IOM DIL	-K-E	Culvert	
T Car Daik	General			rstructure	G/F/P/B	Substructure	G/F/P/B
	Scour		<u> oupe</u>	Stringers	0// // /5	Bndge Seats/Caps	=
Ch	annel/Road			oor Beams		Abuts/Backwalls	Fair
O I I	Approach		Girdere	Truss/Slab	Fair	Piers, Towers, Bents	
	Deck	النصي عبط		Top Flange		Misc	G/F/P/B
Tion //		9/1/10				Guard Rail	-0/1/1/0
	Open Deck)			tom Flange /Diagonals		Guard Rail	<u> </u>
	Fie Spacers Track	Fair		ng Stiffners		<u> </u>	-
	Footwalk	-	Deail	Bracing		 	
		— 				Overall Rating:	Fair
	Handrail	<u> </u>		Bearings MMENTS		Overall Raung:	Fair
51 1 1				WWEN 12	·		
Photo #	Remarks	30 N-4					
	Delcan 200	ge in condition s	Jaco 200E				
 	- NO Chan	ge in condition s	since Zuus	·			
<u> </u>							
 -				· 		_	
						 	-
<u> </u>							
							
	— -						
	Delcan 200	5 Notes:					
<u> </u>		ge in condition s	ince 2004				
	Delcan 200	04 Notes:					
P01	- Approac						
	- Pipe culv						
	UMA 2003						
	- Not Insp						
			ENANCE	RECOMME	NDATIONS	<u> </u>	
Urgency	Descriptio						
	No action	necessary					
					_		
<u> </u>	<u> </u>				_		
	_					_	
					_		

Greenville 103.00

منت سيسب		Brid	ae Inspect	ion Report	-		A THE PARTY OF THE
	3	Mid-Michigan R		ion report			美华 泰亚
	₹ ′	Greenville	allway				
	-	Michigan					
Inspected	Rv:	Stan Reimer	-			19年7年3月	
Inspection		May 22, 2006		DEL	CAN		
Culvert	D0.01	May 22, 2000				2000	· Link
Structure	CMP	Deck Typ		Crossing	Stream		
# Spans	O	Length	<u> </u>	Access	< 1/2 mile		
# Tracks	1	Height	<u>-</u>	Flow Dir	L-R	Greenville 103	00
Year Built	 ;	Alignment	_ _	_1 104 1011		Cuivert	.00
roar Built	General			rstructure	G/F/P/B	Substructure	G/F/P/B
	Scour	Falr	Jupe	Stringers		Bridge Seats/Caps	
Ch.	annel/Road	Fair		oor Beams		Abuts/Backwalls	Fair
Cite	Approach			Truss/Slab	Fair	Piers, Towers, Bents	
	Deck			Top Flange		Misc	G/F/P/B
Tion /		G/F/P/D .		<u> </u>	_ _ _	Guard Rail	————
	Den Deck) Tie Spacers			tom Flange		Guard Kall	
<u>'</u>	Track	 Fair		/Diagonals	<u> </u>		
	Footwalk	_ Fair	Deali	ng Stiffners Bracing			
-	Handrail	<u>-</u>				Overall Rating:	Fair
	nangrali			Bearings		Overall Rating:	- Fair
				MMENTS			
Photo #	Remarks	NO Notes					
P01-P04	Delcan 200	ge in condition (
P01-P04	- NO Chan	Be in cougnion s	since 2005	<u>.</u>			
}-				<u> </u>			
							
							
	-						
<u> </u>							
							-
				-			
	Delcan 200	5 Notes:					
		ge in condition s	ince 2004				
	Delcan 200)4 Notes:					
P01	- Approac						
	- Twin pip						
	UMA 2003				<u></u> -	,	
	- Not insp						
			TENANCE	RECOMME	NDATIONS		
	Descriptio				<u></u>		
	No action	necessary					
ļ							
							. ————
]		_ _					
L							
l	<u></u>						
l ———j	- 						_

EXHIBIT 5 – RESPONSES

United States Department of Agriculture



Helping People Help the Land

Natural Resources Conservation Service
3001 Coolidge Road, Suite 250
East Lansing, MI 48823

T (517) 324-5270/ F (517) 324-5171/ www.ml.nrcs.usda.gov

October 29, 2007

Section of Environmental Analysis Surface Transportation Board 1925 K Street, NW Washington, DC 20423

RE: Docket No. AB-364 (Sub-No. 11X), Mid-Michigan Railroad, Inc. Abandonment Exemption in Kent and Montcalm Counties, MI

We have reviewed the proposal to abandon 26.4 miles of rail line between milepost 104.9 at Lowell Michigan, and milepost 78.5 at Greenville, Michigan. Abandonment of the rail line will not result in the conversion of prime and unique farmland that is located adjacent to the proposed abandonment.

Thank you for this opportunity to comment on this proposal.

Sincerely,

GARRY LEE

State Conservationist

cc:

Louis E. Gitomer, Attorney, 600 Baltimore Ave., Suite 301, Towson, MD 21204 Carla Gregory, Area Conservationist, NRCS, Grand Rapids, MI Steve Utic, District Conservationist, NRCS, Grand Rapids, MI Brian Barclay, District Conservationist, NRCS, Stanton, Ml



United States Department of the Interior

FISH AND WILDLIFE SERVICE Bishop Henry Whipple Federal Building 1 Federal Drive Fort Snelling, MN 55111-4056

FWS/NWRS-RE - General Railroad Abandonments

October 26, 2007

Surface Transportation Board Section of Environmental Analysis (SEA) 1925 K Street, NW Washington, D.C. 20423

Dear Sir/Madam:

Thank you for the opportunity to comment on the proposed abandonment of service on 26.4 miles of railroad line between MP 104.9 and MP 78.5, located in Kent and Montcalm Counties, Michigan, STB Docket No. AB-364 (Sub-No. 11X).

We have researched our ownerships in the vicinity and have determined we do not own any land or interests in land in the vicinity of the proposed rail line abandonments. We do not have any concerns regarding real estate matters in the abandonments.

Sincerely,

/s/ Patrick G. Carroll

Patrick G. Carroll Senior Realty Officer Division of Realty

cc: Louis E. Gitomer, Law Offices of Louis E. Gitomer

EXHIBIT C-FEDERAL REGISTER NOTICE

MID-MICHIGAN RAILROAD. INC.-ABANDONMENT EXEMPTION-IN KENT, IONIA, AND MONTCALM COUNTIES, MI

Notice of Petition for Exemption to Abandonment

On February 20, 2008 Mid-Michigan Railroad, Inc. ("MMRR") filed with the Surface Transportation Board, Washington, D.C. 20423, a petition for exemption for the abandonment of a 24.70-mile rail line between Lowell, milepost 103.20, and Greenville, milepost 78.50, at the end of the line in Kent, Ionia, and Montcalm Counties, MI, all of which traverses through United States Postal Service ZIP Codes 48809, 48838, 48887, and 49331 (the "Line") The Line for which the abandonment exemption request was filed includes the stations of Lowell, Belding, and Greenville

The Line does not contain federally granted rights-of-way. Any documentation in the railroad's possession will be made available promptly to those requesting it.

The interest of railroad employees of MMRR will be protected by *Oregon Short*Line R Co—Abandonment—Goshen, 360 I.C.C. 91 (1979).

MMRR has requested the Board to grant an exemption from the offer of financial assistance process. If the exemption is not granted, any offer of financial assistance will be due no later than 10 days after service of a decision granting the petition for exemption. All interested persons should be aware that following abandonment of rail service and salvage of the line, the line may be suitable for other public use, including unterim trail use

Any request for a public use condition and any request for trail use/rail banking will be due no later than 20 days after notice of the filing of the petition for exemption is published in the Federal Register.

MMRR has proposed, and we are adopting the following procedural schedule for this proceeding.

February 20, 2008—Petition for Exemption filed.

March 11, 2008—Due date for Notice of Petition to be published in the *Federal Register*.

April 4, 2008—Due date for protests and comments, including opposition case in chief, and for public use and trail use requests.

April 16, 2008—Due date for MMRR's reply to opposition case and for MMRR's response to trail use requests.

June 6, 2008—Due date for service of decision on the merits.

June 16, 2008—Due date for offers of financial assistance, unless exempted by the Board.

Persons seeking further information concerning abandonment procedures may contact the Surface Transportation Board or refer to the full abandonment or discontinuance regulations at 49 CFR Part 1152. Questions concerning environmental issues may be directed to the Board's Section of Environmental Analysis. An environmental assessment (EA) (or environmental impact statement (EIS), if necessary) prepared by the Section of Environmental Analysis will be served upon all parties of record and upon any agencies or other persons who commented during its preparation. Any other persons who would like to obtain a copy of the EA (or EIS) may contact the Section of Environmental Analysis. EAs in these abandonment proceedings normally

will be made available within 60 days of the filing of the petition. The deadline for submission of comments on the EA will generally be within 30 days of its service.

EXHIBIT D-NEWSPAPER CERTIFICATION

CERTIFICATE OF PUBLICATION

The undersigned hereby certifies that notice of the proposed abandonment in Docket No. AB-364 (Sub-No. 14X) was advertised on February 19, 2008 in the Grand Rapids Press, a newspaper of general circulation in Kent, Ionia, and Montcalm Counties. MI, as required by 49 C.F.R. § 1105.12.

Louis F. Gitomer

Mid-Michigan Railroad, Inc. ("MMRR") gives notice that on or about February 20, 2008 it intends to file with the Surface Transportation Board, Washington, DC 20423, a petition for exemption under 49 U.S.C. 10505 from the prior approval requirements of 49 U.S.C. 10903, et seq., permitting the abandonment of a 24.7-mile rail line between milepost 103.2 near Lowell and milepost 78.5 near Greenville at the end of the line, which traverses through United States Postal Service ZIP Codes 48809, 48838, 48887, and 49331 in Kent, Ionia, and Montcalm Counties, MI (the "Line"). The proceeding has been docketed as No. AB-364 (Sub-No. 14X).

The Board's Section of Environmental Analysis (SEA) will generally prepare an Environmental Assessment (EA), which will normally be available 60 days after the filing of the petition for abandonment exemption. Comments on environmental and energy matters should be filed no later than 30 days after the EA becomes available to the public and will be addressed in a Board decision. Interested persons may obtain a copy of the EA or make inquiries regarding environmental matters by writing to SEA, Surface Transportation Board, Washington, DC 20423 or by calling SEA at 202-245-0295

Appropriate offers of financial assistance to continue rail service can be filed with the Board. Requests for environmental conditions, public use conditions, or rail banking/trails use also can be filed with the Board. An original and 10 copies of any pleading that raises matters other than environmental issues (such as trails use, public use, and offers of financial assistance) must be filed directly with the Board's Office of the Secretary, 395 E Street, SW, Washington, DC 20423 [See 49 CFR 1104.1(a) and 1104.3(a)], and one copy must be served on applicants' representative [See 49 CFR 1104.12(a)]. Questions regarding offers of financial assistance, public use or trails use may be directed to the Board's Office of Congressional and Public Services at 202-245-0233. Copies of any comments or requests for conditions should be served on the applicant's representative: Louis E. Gitomer, Law Offices of Louis E. Gitomer, 600 Baltimore Avenue, Suite 301, Towson, MD 21204. (410) 296-2250, Lou_Gitomer@verizon.net.

EXHIBIT E-CERTIFICATE OF SERVICE

CERTIFICATE OF SERVICE

Pursuant to 49 C.F.R. §1152.60(d), the undersigned hereby certifies that the Petition for Exemption in Docket No. AB-364 (Sub-No. 14X), *Mid-Michigan Railroad*. *Inc Abandonment Exemption—in Kent. Ionia, and Montealm Counties, MI* was mailed via first class mail, postage prepaid, on February 20, 2008, to the following parties:

State Public Service Commission

1

Michigan Department of Transportation P.O. Box 30050 Lansing, MI 48909

Public Service Commission 6545 Mercantile Way, Suite 7 Lansing, MI 48909

Military Surface Deployment and Distribution Command Transportation Engineering Agency

SDDC FEA
AT FN Railroads for National Defense
720 Thimble Shoals Blvd.
Suite 130
Newport News, VA 23606-2574

National Park Service

U.S. Department of Interior National Park Service Land Resources Division 1201 Eye Street, N.W. Washington, DC 20005

Ms. Cherri Espersen
National Recreation Trail Coordinator
Rivers, Trails and Conservation Assistance Program National Park Service
1849 C Street, NW (Org Code 2240)
Washington, DC 20240-0001

U.S. Department of Agriculture

U S. Department of Agriculture Chief of the Forest Service 4th Floor, NW Sidney R. Yates Building 201 14th Street, S.W. Washington, DC 20250

> Louis E. Gitomer February 20, 2008

EXHIBIT F-MARK D. GARVIN VERIFIED STATEMENT

Docket No. AB-364 (Sub-No. 14X)

MID-MICHIGAN RAILROAD, INC.—ABANDONMENT EXEMPTION— IN KENT, IONIA, AND MONTCALM COUNTIES, MI

VERIFIED STATEMENT OF MARK D. GARVIN

My name is Mark D. Garvin and I am Chief Engineer of RailAmerica, Inc. ("RailAmerica"), a shortline holding company that controls Mid-Michigan Railroad, Inc. ("MMRR"). I have a B.S. in Civil Engineering from Michigan Technological University. My engineering work in the railroad industry began over 25 years ago on Conrail as a management trainee. I soon became an assistant track supervisor in charge of track maintenance. I joined Grand Trunk Western Railroad Company as a track supervisor, in charge of system track gangs performing capital projects. I joined RailAmerica as a Project Manager and became Chief Engineer in January 1992. My current duties include the acquisition of track equipment and material, the selection and training of maintenance of way personnel, the engineering evaluation of potential acquisition properties, and the development of maintenance and rehabilitation plans for properties acquired by RailAmerica.

I am familiar with the 24.70-mile rail line between Lowell, milepost 103.20, and Greenville, milepost 78.50, at the end of the line in Kent, Ionia, and Montcalm Counties, MI (the "Line").

I will discuss the value of the track and materials on the Line, the cost of rehabilitation of the Line, and the annual maintenance-of-way costs once the Line is rehabilitated.

1. Value of Track and Materials. Each of RailAmerica's subsidiary railroads maintain an inventory of track and materials on its lines under my supervision as Chief Engineer. In addition, each railroad conducts regular inspections of its lines to maintain the accuracy of the inventory and the condition of the inventory. Attached as the Exhibit to this verified statement is the list of inventory on the Line.

The inventory includes rail, other track material ("OTM"), ties, signals and turnouts. The rail, OTM, and turnouts are classified as relay, reroll, or scrap. The valuations are based on recent quotations obtained by MMRR and RailAmerica from rail suppliers and quotations in national publications. Liquidation costs are based on my experience with the cost of removal and transportation and recent quotations received by MMRR and RailAmerica for removal and transportation

Although the Exhibit values ties, I have been told that the trail user has indicated a desire to retain the ties. This is a benefit of \$42,525 to MMRR since it will cost more to remove and transport the ties (\$323,190), than their value (\$280,665). Therefore, the net liquidation value of the railroad asset will be \$2,460,077.

- 2. Rehabilitation. It is my judgment based on my long experience in the railroad industry that \$125,000 in capital expenditures is required to rehabilitate the Line so that it will remain in Federal Railroad Administration Class 1 condition. MMRR will replace 1,700 ties. MMRR will resurface the entire Line once the ties are replaced in order to ensure a relatively smooth surface to operate over.
- 3. Maintenance-of-way. I have reviewed with the four Field Chief Engineers for the RailAmerica railroads the recent costs per mile adopted by the Surface Transportation Board for Class III railroads for maintenance of way costs. Those costs

range between \$4,500 and \$6,000 per mile. Based on consultation and experience, I believe use of \$5,000 per mile is conservative. The reason that I believe such cost is valid is based on the costs to be incurred in the initial maintenance of the Line of \$235,000, which consists of brush cutting costs of \$38,000, D Car rail \$100,000, \$75.000 to replace ties and resurface rail, and \$22,000 to clear water ways and repair washouts.

In addition, there are inspection costs on the Line. The Line is inspected on a weekly basis by one employee. The inspection usually takes three to five hours to complete. The hourly wages for an employee inspecting track on MMRR are \$15.88. In addition, employee benefits are about 71.02 percent of wages, and general administrative costs of 50 percent of wages. Therefore, to inspect the Line costs about \$40.70 per hour. Based on the average amount of time it takes to inspect the Line of four hours per week, inspection costs MMRR \$162.80 per week, and \$8,465.60 per year.

On this 24.70-mile line, the average per mile cost of maintenance would be about \$9,856. Therefore, in my professional judgment and based on my experience, I feel very confident using an average maintenance of way cost of \$5,000 per mile or \$123,500 for the Line.

VERIFICATION

I, Mark D Garvin, verify under penalty of perjury under the laws of the United States that the foregoing is true and correct Further, I certify that I am qualified and authorized to file this Verified Statement.

Executed on February 14, 2008.

Mark D. Garvin

EXHIBIT

Liquidation Value of Railroad Asset

MMRR - Greenville Sub - MP 103.2 - 78.5

November 14, 2007

					Rail					
Weight	Jnt./CWR	Miles	NT/Mile	Total NT	Total GT	Class	Price NT	Price GT	Total S NT	Total S GT
HOIP	Jnt	5 65	183 92	1039 15	927 81	Relay	\$550		\$571,531	
1121Ь	Jnt	19	187 26	355.80	317.68	Relay	\$600		\$213,481	
1221Ь	Jnt	0 1	203 98	20 40	18 21	Relay	\$500		\$10,199	
1301Ь	CWR	2	217 36	434.72	388.14	Relay	\$650		\$282,568	
131lb	CWR	48	219 03	1051 35	938.71	Relay	\$650		\$683,380	
13116	Jnt	12	219 03	262 84	234 68	Relay	\$600		\$157,703	
11016	Jnt	2 65	183 92	487 39	435 17	Reroll		\$ 335		\$145,781
131Њ	Jnt	09	219 03	197 13	176 01	Reroll		\$335		\$58,963
90lb	Jnt	6 88	150 48	1035 30	924 38	Reroll		\$335		\$309,666
90lb	Jnt	2 27	145 73	330.80	295 36	Scrap		\$240		\$70,886
Totals		28.35		5214.88	4656.14		Total Ra	ail Value	\$2,50	4,159

					OTM					
Weight	Jnt./CWR	Miles	N I /Mile	Total NT	Total GI	Class	Price \T	Price G [Total \$ NT	Total \$ GT
Holb	Jnt	83	57 0	473 10	422.41	Relay	\$350		\$165,585	
112lb	Jnt	19	84 0	159.60	142.50	Relay	\$350		\$55,860	
122lb	Jnt	0 1	86 0	8 60	7 68	Relay	\$ 350		\$3,010	
130lb	CWR	2	82 5	165.00	147 32	Relay	\$350		\$57,750	
131lb	CWR	48	82 5	396 00	353 57	Relay	\$350		\$138,600	
131lb	Jnt	12	93.2	11184	99 86	Relay	\$350		\$39,144	
131lb	Jnt	09	93 2	83 88	74 89	Scrap		\$265		\$19,847
90lb	Jnt	6 88	50 0	344 00	307 14	Scrap		\$265		\$81,393
901Ъ	Jnt	2 27	50 0	113 50	101.34	Scrap		\$265		\$26,855
Totals		28.35		1855.52	1656.71	•	Total OT	'M Value	\$588	.043

		Ties (R	emoval/& M	arket)					
Class	%	Miles	Total Ties	Price Ea.	Total		Signa	l Appliances	
#1 Kelay	10%	28 4	8505	\$8	\$68,040	Type	Quantity	Unit Price	Total
#2 Relay	25%	28 4	21262 5	\$ 6	\$127,575	Lights	12	\$2,500	\$30,000
Landscape	25%	28 4	21262 5	\$4	\$85,050	Gates	0	\$3,500	
Scrap	40%	28 4	34020	\$0			Total a	all Signals	\$30,000
			Tota	1 Tie Value	\$280,665				

			. C. 152	***************************************	Turnouts		, .			
Weight	Type	Qty.	NT/TO	Total NT	Total GT	Class	Price EA	Price GT	Total S Each	Total S GT
131 <i>l</i> b	No 10	. 8	4 65	37.20	33.21	relay	\$8,000		\$64,000	
1121b	No 10	3	4 52	13.56	12 11	scrap		\$265		\$3,208
1 I 01b	No 10	3	4 50	13 50	12 05	scrap		\$265		\$ 3,194
1101b	No 10	1	4.50	4 50	4 02	scrap		\$265		\$1,065
90lb	No 10	2	1.93	3 86	3 45	scrap		\$265		\$913
Totals		17		72.62	64.84		Total OT	M Value	\$72,	381

	Liquida	tion Costs		
	Unit	Cost	Quantity	Total
Dismantle Track (CWR)	Nľ	\$ 65	2047 N I	\$133,059 8
Dismantle Trk (Jointed)	NT	\$ 50	4339 NT	\$216,940 6
Transport Rail & OTM	NT	\$ 35	7143 NT	\$250,005 8
Remove Ties	EΛ	\$2	85,050	\$170,100 0
Transport Ties	EΛ	\$3	51,030	\$153,090 0
Remove Relay Turnouts	ĿA	\$2,500	17	\$42,500 0
Remove Crossing Signal	EA	\$1,500	12	\$18,000 0
Restore Crossings	EA	\$2,000	37	\$7 9,9 00.0

संबर्धी (तवीमधीपार्गियी विकर्ष	\$1,057,696
<u> </u>	<u>. </u>
Fice Metally in the Control of the C	\$2,417,55

EXHIBIT G-ROBERT M. FRELICH, JR. VERIFIED STATEMENT

Docket No. AB-364 (Sub-No. 14X)

MID-MICHIGAN RAILROAD, INC.-ABANDONMENT EXEMPTIONIN KENT, IONIA, AND MONTCALM COUNTIES, MI

VERIFIED STATEMENT OF ROBERT M. FRELICH, JR.

My name is Robert M. Frelich, Jr. and I am Director of Finance of RailAmerica, Inc. ("RailAmerica"), a shortline holding company that controls Mid-Michigan Railroad, Inc. ("MMRR"). The purpose of this verified statement is to describe how I developed the revenues and costs of MMRR over the 24.70-mile rail line between Lowell, milepost 103.20, and Greenville, milepost 78.50, at the end of the line in Kent, Ionia, and Montcalm Counties, MI (the "Line").

I have been Director of Finance for last two years and was Director of Planning for prior nine years with RailAmerica. As Director of planning, I was responsible for planning, analyzing traffic profitability and financial results, acquisition modeling, and budgeting for RailAmerica's subsidiary railroads. My prior experience with Southern Pacific was as Director of Budgeting for Operating Department.

My current duties include responsibility for planning, cost modeling, profitability analysis, analyzing financial results, acquisition modeling and budgeting of railroads for two regions.

1. Background. The Surface Transportation Board (the "Board") has developed a very sophisticated methodology in 49 C.F.R. Part 1152 Subpart D for calculating revenues and avoidable costs of a line of railroad that a railroad is seeking to abandon. The predicate for using these procedures is maintaining data in accordance with the Branch Line Accounting System (the "BLAS"). Only Class I railroads are required to

maintain records in accordance with the BLAS. As a Class III railroad, MMRR does not maintain its records in accord with the BLAS.

Using the data and resources available to me from the MMRR, I have tried to present the Board with an accurate analysis of the revenue generated by the Line and the costs of operating the Line. In conducting this analysis, I have developed a Forecast Year based on traffic from customers on the Line who will continue you use rail service.

- 2. Forecast Year Traffic. The main customer on the Line, Frigidaire

 Corporation moved its facility to South Carolina and Mexico in early 2006 and made its

 last shipment over the Line in April 2006. Since Frigidaire stopped using rail service on
 the Line, the only user of service has been Crop Production Service ("CPS"). In 2006,

 CPS shipped one car in December. CPS has not used rail service on the Line in 2007 or
 2008 to date. Therefore, I will calculate the revenues and costs of operation based on the
 annual shipment of one carload.
 - 1. Revenue. Revenue generated by CPS on the Linc in 2006 was \$494.00.
- 2. Avoidable Costs. In calculating the avoidable costs of operating over the Line, I will determine the costs of operation and use the costs to maintain the Line prepared by Mr. Garvin.
- a. Costs of Operation. The cost to operate a train on the Line depend on the amount of time spent on the Line, the numbers of trips on the Line, the number of employees and their compensation, the number of locomotives used and their cost, the cost of fuel, and the overhead costs that include general and administrative costs, depreciation, and the maintenance of way costs as developed by Mr. Garvin.

An average trip to serve CPS takes about six hours round trip. Each time CPS is served, it requires two trips, one to drop off a car and another to pick up the car. Because MMRR is serving CPS once per year, MMRR cannot combine trips to pick up and deliver cars at the same time.

In 2008, there are two people in the train crew serving CPS. I foresee a two person train crew for at least the next two years, including the Forecast Year. Hourly wages for each crew member is \$17.21 per hour and their benefits are equal to about 71.02 percent of wages. Therefore, for the two six hour trips to CPS, MMRR's employee costs are \$706.38 (2x2x6x17.21x1.7102).

MMRR uses one 2000 horsepower locomotive to serve CPS. Daily rental of the locomotive from RailAmerica is \$114.00. The locomotive burns about 6.5 gallons per hour based on grade and amount of tonnage being hauled, and for 2007, the average cost per gallon was \$2.27. I do not foresee the cost of fuel dropping in 2008. The locomotive fuel cost for two six hour trips is \$177.06 ((2x6x6.5x2.27) and the locomotive rental is \$57.00 (114x2x6/24)).

Based on the above costs; \$706.38 (crew costs) plus \$177.06 (locomotive fuel) plus \$57.00 (for locomotive rental) and \$470.22 (50% for overhead), the total yearly costs are \$1,410.66

- b. Maintenance of Way Costs. Mr. Garvin has developed an annual maintenance of way cost of \$123,500 for the Line, which I adopt and will use.
- c. Summary of Avoidable Costs. The annual operating costs on the Line are \$1,410.66. Annual maintenance of way costs on the Line are \$123,500. Total avoidable costs on the Line are \$124,910.66

3. Avoidable losses. The annual revenue projected for the Line is \$494.00.

Annual avoidable costs are \$124,910.66, resulting in an avoidable loss of \$124,416.66.

103

VERIFICATION

I, Robert M. Frelich, Jr., verify under penalty of perjury under the laws of the United States that the foregoing is true and correct. Further, I certify that I am qualified and authorized to file this Verified Statement.

Executed on February 15, 2008.

Robert M. Frelich, .

EXHIBIT H-TODD N. CECIL VERIFIED STATEMENT

Docket No. AB-364 (Sub-No. 14X)

MID-MICHIGAN RAILROAD, INC.-ABANDONMENT EXEMPTION-IN KENT, IONIA, AND MONTCALM COUNTIES, MI

VERIFIED STATEMENT OF TODD N. CECIL

My name is Todd N. Cecil. I am employed as Vice President-Real Estate, for RailAmerica, Inc., and the Mid-Michigan Railroad, Inc. ("MMRR"). My credentials are provided in the attached Exhibit. The purpose of this statement is to provide the Surface Transportation Board with the valuation of the real estate on the 24.7-mile rail line between Lowell, milepost 103.20, and Greenville, milepost 78.50, at the end of the line in Kent, Ionia, and Montcalm Counties, MI (the "Line").

I have negotiated a Memorandum of Understanding (the "MOU") with the West Michigan Trails and Greenways Coalition to sell the real estate in the Line and the 15.83-mile rail line between southeast of Lowell, milepost 137.83, and east of Prairie Center, milepost 122.00, the end of the line, in Kent and Ionia Counties, MI for interim trail use/rail banking. Based on these negotiations, I expect to sell both lines for about \$2,300,000. Based on the acreage and other relevant factors, the Line contains about 56 percent of the value in the transaction or \$1,288,000. In my professional opinion, this is a very reasonable valuation for the Line.

VERIFICATION

Todd N. Cecil

I, Todd N. Cecil, verify under penalty of perjury under the laws of the United States that the foregoing is true and correct. Further, I certify that I am qualified and authorized to file this Verified Statement.

Executed on February 15, 2008.

107

EXHIBIT-QUALIFICATIONS OF MR. CECIL

My office address is 1355 Central Parkway South, Suite 700, San Antonio, Texas 78232. I have been employed by RailAmerica since its acquisition of RailTex, Inc. in February 2000. Prior to that time I was employed by RailTex for seven years (since February 1993), most recently in the position of Vice President – Real Estate.

My current duties and responsibilities include the management, development and disposition of the various real estate interests included within RailAmerica's international railroad portfolio. These real estate interests are located all throughout the U.S., Canada and Chile. Included in my duties are the appraising of various interests in railroad-owned real estate, reviewing the appraisals of others, and handling negotiations for sales, leases, acquisitions and other real estate transactions.

My prior railroad-related real estate experience consists of ten years with various subsidiaries of CSX Transportation, Inc. (including Chessie Resources, Inc., CSX Resources, Inc., Chessie Systems, and CSX Real Property, Inc.) between 1980 and 1990. During this period I rose through the corporate ranks to the level of Regional Manager, Great Lakes, with responsibility for the management of all CSX real estate holdings in Michigan, Ontario, and portions of Indiana and Illinois (including Chicago).

Also, for three years between my employment with CSX and RailTex (1990-1993), I was employed by Trerice Tosto, a metro-Detroit full-service real estate company in the position of Vice-President of the Appraisal and Consulting Division. During this time I was involved in the appraisal of many types of income producing properties (including industrial, commercial, residential and special purpose properties), and also

provided corridor and other real estate valuation consulting services to railroad and utility companies.

I am a 1977 graduate of Bowling Green State University (Bowling Green, Ohio) with a Bachelor of Arts Degree in Geography (Regional Planning). I also earned a Master of Arts Degree in Geography from the same university in 1980.

I have successfully completed numerous real estate appraisal courses offered by the Appraisal Institute (formerly the American Institute of Real Estate Appraisers) including:

Real Estate Appraisal Principles

Basic Valuation Procedures

Capitalization Theory and Technique - Part 1

Capitalization Theory and Technique - Part 2

Capitalization Theory and Technique - Part 3

Case Studies in Real Estate Valuation

Valuation Analysis and Report Writing

Investment Analysis

Standards of Professional Practice

Real Estate Disclosure

Litigation Valuation

Internet Search Techniques for Real Estate Appraisers

GIS Applications for Real Estate Appraisal

Appraising From Blueprints and Specifications

Analyzing Operating Expenses

Business Practices and Ethics

In summary, my professional railroad real estate experience includes over 20 years of appraising, selling, leasing, and managing railroad properties. Included in this experience are numerous railroad corridor valuation and disposition projects. These

properties include numerous railroad corridors and railroad corridor segments (including urban, suburban, and rural) running through diverse neighborhood types and consisting of a wide spectrum of highest and best uses.

I have also prepared and reviewed appraisals and valuation studies of virtually all types of property (commercial, industrial, residential, special purpose, railroad corridors, etc.) located in over twenty (20) states located throughout the country, in Canada, and in Chile.

In addition, over the years I have been involved in negotiating hundreds of purchase, lease and sale transactions involving railroad real estate properties. This experience has provided me with unique insight into the value potential of railroad real estate, the potential motivations of purchasers for these properties, as well as a feel for the marketability of railroad properties of nearly all potential land uses.

EXHIBIT I–ROBET DINE VERIFIED STATEMENT

Docket No. AB-364 (Sub-No 14X)

MID-MICHIGAN RAILROAD. INC.—ABANDONMENT EXEMPTION— IN KENT, IONIA, AND MONTCALM COUNTIES, MI

VERIFIED STATEMENT OF ROBERT DINE

My name is Robert Dine. I am employed as Assistant General Manager, for the Mid-Michigan Railroad, Inc. ("MMRR"). My address is 432 East Grove Street, Greenville, MI 48838. The purpose of this statement is to confirm that the last traffic to move over the 24.7-mile rail line between Lowell, milepost 103.20, and Greenville, milepost 78.50, at the end of the line in Kent, Ionia, and Montcalm Counties. MI (the "Line") occurred in December 2006.

I am responsible for all operations on the MMRR. Part of my responsibility is to be aware of the traffic moving over all of the lines the MMRR. I have reviewed the MMRR's records and can conclude that no traffic moved over the Line in 2007 and none has moved so far in 2008. In addition, the beginning of the abandonment in Lowell is north of any existing shippers who use the Line so that they will continue to receive service after the Line is abandoned.


VERIFICATION


I, Robert D. Dine, verify under penalty of perjury under the laws of the United States that the foregoing is true and correct. Further, I certify that I am qualified and authorized to file this Verified Statement.


Executed on February 8, 2008.


Robert D. Dine


EHHIBIT J-COLOR EXHIBITS




















Greenville 81.10

		Reid	ae Inenect	ion Report			A STATE OF		
	~	Mid-Michigan R		on Keport			1		
	≈	Mid-Michigan R Greenville	anway						
						- 133. 14. 5	£ , .		
	Ď	Michigan		ı		1 1 1 1 1 1 1 1 1	25.48		
Inspected		Stan Reimer	- -	DELCAN					
Inspection		May 22, 2006					麗 】		
	estie Struct						100 0000000000000000000000000000000000		
Structure		Deck Typ	Bailast	Crossing	River		38		
# Spans	13	Length [,]	175	_ Access_	< 1/2 mile				
# Tracks	1	Height		Flow Dir	R-L	Greenville 81.	10		
Year Built	1943	Alignment C				Flat River			
	General	G/F/P/B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B		
	Scour	Fair		Stringers	_ Poor	Bridge Seats/Caps	Bad		
Cha	annel/Road	Poor		loor Beams	!	Abuts/Backwalls	Poor_		
	Approach	Fair	Girders	/Truss/Slab		Piers, Towers, Bents	Poor		
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B		
	Ties	Fair	Bot	tom Flange		Guard Rail			
1	Tie Spacers			/Diagonals					
	Track	Fair	Bean	ng Stiffners					
	Footwalk			Bracing					
	Handrail			Bearings		Overall Rating:	Poor		
	· 		CO	MMENTS		· 			
Photo #	Remarks	-							
1 11010 11	Delcan 20	06 Notes:							
P11-P12		cap crushing - u	raent repl	acement st	ili required				
P10		piles 2 and 6 pu							
		<u> </u>			<u> </u>				
	Delcan 20	05 Notes:							
P01	- Approac	hes low							
P06-P09	- Bent 11	- urgent pile car	replacem	ent from la	st year not	yet done - cap crushir	ng —		
		piles 2 and 3 pu							
	- Bent 8 -	piles 2 and 6 pu	nky (piles	4 and 5 sec	m to be O	K)			
	Delcan 20	04 Notes:							
P01	- Approac	hes uneven							
P03		leck ties OK							
P04	- Inspecte	d under traffic -	n <u>o pumpi</u>	ng <u>evident</u>	near first a	pproach			
<u> </u>	B <u>ent</u> 6 -	<u>pile 4 hollow, pl</u>	le 6 OK		_				
L		<u>pile 2 hollow, pi</u>			<u> </u>				
		piles 2, 4 and 5			<u>line</u> _	<u> </u>			
		pile 6 punky ner			_				
		<u>- pile 4 is punky</u>			-				
_ <u>P09</u> _		- pile cap crush		replaceme	nt <u>reguire</u>	<u> </u>			
P02	<u> - Debris ii</u>	channel on rig							
			TENANCE	RECOMME	NDATION:	<u> </u>			
Urgency									
Urgent_									
3 years		<u>8 - piles 2 and</u> 6	- <u>\$5</u> ,000						
5 years		<u>\$ - \$20,00</u> 0							
	Ba <u>nding p</u>	rogram for bent	14 pile ca	<u> P</u>	. ——	_			
<u></u>									

Greenville 81.60

		Brid	ge Inspect	ion Report			0.50			
	~	Mid-Michigan R		.on troport		The state of the s	1,10,12			
	3	Greenville	y							
		Michigan				وسويسوله أسال المراسين والمستوان	- T			
Inspected	Bv:	Stan Reimer		I						
Inspection		May 22, 2006	— - DELCAN			ļ.,				
		ers/Beams)								
Structure	DPG	Deck Typ	Open	Crossing	Stream		9			
# Spans	- 2	Length	100	Access	< 1/2 mile		200			
# Tracks		Height		Flow Dir	R-L	Greenville 81	60			
Year Built	1910		Alignment T			Stream				
Tour Donc	General		Substructure	G/F/P/B						
	Scour	Fair	Bridge Seats/Caps	Fair						
Cha	annel/Road	Fair		Stringers loor Beams	Fair	Abuts/Backwalls	Poor			
J	Approach	Fair -		/Truss/Slab	Fair	Piers, Towers, Bents	<u>Роог</u>			
	Deck			Top Flange	Fair	Misc	G/F/P/B			
T:00 /6		Fair				Guard Rail				
	Open Deck) Tie Spacers	rair Fair		tom <u>Flange</u> Dagonals		Guaru Raji				
<u>'</u>	Track	- Fair		ng Stiffners	Fair					
	Footwalk		Deall	Bracing	Fair					
	Handrail			Bearings		Overall Rating:	Fair			
	Haliulali			MMENTS	ган	Overall Natility.	ran			
Dhata #	Domoska	**		MINENIS						
Photo #	Remarks Delcan 20	ne Netec								
- P01		proach a bit low	this year							
- F01 -		ck - 12 reject tie		,						
P09		ight side - moni			or now		— — ·			
	-1.161 1 - 1	gir side - Illoill	toring crac	King - OK	101 11011					
· — —	Delçan 20	05 Notes:			· -					
	- Approac									
		ct ties (6%)								
	Delcan 20					_				
P01		hes a bit low				_				
P03		ct ties (5%)								
P12,P06	- Pier 1 - c	rack below righ	t bearing o	on upmile fa	ace only - a	monitor				
P08	- Abutme	nt 1 - right beari	ng seat - s	ome cracki	ng at previ	ous repair - monitor				
	UMA 2003	Notes:								
						crete. Backwall is				
				<u>ns. Pier 1 c</u>	c <u>oncrete is</u>	scaling. Plan on cond	rete			
	repairs to	pier and abutme								
			TENANCE	RECOMME	NDATION	<u> </u>				
Urgency										
Monitor	Crack on upmileage face of Pier 1									
$oldsymbol{L} = -$										
		<u> </u>								
						_ 				

Greenville 87.40

Bridge Inspection Report												
Inspected By: Stan Reimer May 22, 2008 Comment May 22, 2008 Comment Ma	**************************************	92.			ion Report			1'				
Inspected By: Stan Reimer May 22, 2008 Comment May 22, 2008 Comment Ma				ailway								
Inspected By: Stan Reimer May 22, 2006 May 22, 2006 May 22												
Inspection Date: Inspection Date: Inspection Date: Impert Trestle Structure with Steel Mainspan(s) Structure PT/DPO #Spans 7 #Channel PT/DPO #Tracks 1 Height Flow Dir Year Built 1914 Alignment T Scour Fair Superstructure GF/P/B Substructure GF/P/B Bridge Seats/Caps Fair Abuts/Backwalls Fair Fair Dof Fair Fair Fair Fair Guard Rail Track Fair Beaning Stiffners Fair Guard Rail Beaning Stiffners Fair Guard Rail Beaning Stiffners Fair Overall Rating: Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now Delcan 2004 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 7 - Stringer 1 rotten Delcan 2004 Notes: - Approaches high - P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splittling vertically MAINTENANCE RECOMMENDATIONS Urgency Description							National International	the law later				
Timber Trestle Structure with Steel Mainspan(s) Structure PT/DPG Deck Typ Open Crossing River 12 mile Flat River Tracks 1 Height Flow Dir Flat River Flat Riv					DELC	CAN		72				
Structure PT/DPG Deck Typ Open Crossing River Height 165 Access' 12 mile Flat River Regular 1914 Alignment T Flat River Flat Ri												
# Spans 7 Length 165 Access < 1/12 mile Greenville 37.4 # Tracks 1 Height Flow Dir Year Built 1914 Alignment T General GFP/8 Superstructure GFP/8 Substructure GFP/8 Scour Fair Stringers Poor Bridge Seats/Caps Fair Approach Fair Girders/Truss/Slab Fair Approach Fair Girders/Truss/Slab Fair Deck GFP/8 Top Flange Fair Ties (Open Deck) Poor Bottom Flange Fair Footwalk Fair Beanings Fair Footwalk Bearings Fair Delcan 2006 Notes: P12	Timber Tro			lainspan(s								
#Tracks 1 Height Year Built 1914 Alignment T Flow Dir Greenville 87.4 Flat River General G/F/P/B Superstructure G		PT/DPG_	Deck Typ		Crossing							
Year Built 1914 Alignment T Superstructure G/F//B Substructure G/F//B Fair Substructure G/F//B Fair Floor Beams Approach Fair Girders/Truss/Slab Fair Piers, Towers, Bents Fair Deck G/F//B Top Flange Fair Guard Rail Fair Guard Rail Fair Beaning Fair Guard Rail Fair Beaning Fair Guard Rail Fair Beaning Fair Guard Rail Beaning Fair Guard Rail Fair Footwalk Beanings Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P08 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description		7		165		< <u>1/2</u> mile						
General GIFIP/B Superstructure GIFIP/B Substructure Scour Fair Stnngers Poor Bridge Seats/Caps Fair Floor Beams Abuts/Backwalls Fair Floor Beams Abuts/Backwalls Fair Fair Floor Beams Abuts/Backwalls Fair Pers, Towers, Bents Fair Deck GIFIP/B Top Flange Fair Pers, Towers, Bents Fair Tes (Open Deck) Poor Bottom Flange Fair Guard Rall Track Fair Beanng Stiffners Fair Fair Footwalk Bracing Handrall Bearings Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 1 - stringers 2 and 8 split but OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (17%) - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high - 17/99 reject ties (17%) - Span 1 - stringer 2 splitting vertically Comments P04 - Span 1 - stringers 2 and 8 split but OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P05,P06 - Span 1 - stringers 2 and 8 split P04 - Span 7 - Stringer 1 rotten P05,P06 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers 2 and 8 split P05 - Span 1 - stringers P05 - Span 1 - string		•				7.4						
Scour Fair Stnngers Poor Abuts/Backwalls Fair Floor Beams Abuts/Backwalls Fair Fair Gres/Truss/Slab Fair Piers, Towers, Bents Fair Deck Top Flange Fair Web/Diagonals Fair Track Fair Beaning Stiffners Fair Footwalk Beaning Stiffners Fair Fair Fair Fair Footwalk Beaning Stiffners Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringer 1 rotten Delcan 2004 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 7 - Stringer 1 rotten Delcan 2004 Notes: - P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	Year Built	1914_	Alignment				Flat River					
Channel/Road Approach Fair Griders/Truss/Slab Fair Piers, Towers, Bents Fair Deck Grif/P/B Top Flange Fair Top Flange Fair Top Flange Fair Ties (Open Deck) Poor Bottom Flange Fair Web/Diagonals Fair Track Fair Beaning Stiffners Fair Footwalk Bracing Fair Track Fair Beaning Stiffners Fair Footwalk Bracing Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: - P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description		General	G/F/P/B	Supe	erstructure	G/F/P/B	Substructure	G/F/P/B				
Approach Fair Girders/Truss/Slab Fair Piers, Towers, Bents Fair Deck G/F/P/B Top Flange Fair Misc G/F/P/B Ties (Open Deck) Poor Bottom Flange Fair Guard Rail Fair Tresk Fair Web/Diagonals Fair Web/Diagonals Fair Bearing Stiffners Fair Bearing Fair Footwalk Bearings Fair Fair Bearing Fair Fair Footwalk Bearings Fair Fair Bearings Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description		Scour	Fair		Stringers	Poor	Bridge Seats/Caps	Fair				
Deck G/F/P/B Top Flange Fair Misc G/F/P/B	Cha	annel/Road	Fair	F	loor Beams		Abuts/Backwalls	Fair				
Ties (Open Deck) Tie Spacers Fair Track Fair Beaning Stiffners Fair Beaning Stiffners Fair Footwalk Handrail Beaning Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	<u> </u>	Approach	Fair	Girders	/Truss/Slab	Fair	Piers, Towers, Bents	Fair T				
Ties (Open Deck) Poor Bottom Flange Fair Guard Rail Tie Spacers Fair Web/Diagonals Fair Track Fair Beaning Stiffners Fair Footwalk Beaning Fair Overall Rating: Fair Handrail Beanings Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description			G/F/P/B	— – .	Top Flange	Fair	Misc	G/F/P/B				
Tie Spacers Fair Web/Diagonals Fair Track Fair Bearing Stiffners Fair Bracing Fair Bracing Fair Totvalk Bracing Fair Bearings Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P03, P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	Ties (C		<u> </u>	_				,				
Track Footwalk Bracing Bearing Stiffners Fair Bearing Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description			Fair					<u> </u>				
Footwalk Bracing Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description												
Handrail Bearings Fair Overall Rating: Fair COMMENTS Photo # Remarks Delcan 2006 Notes: P12												
Photo # Remarks Delcan 2006 Notes: P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	_	Handrail					Overall Rating:	Fair				
Photo # Remarks Delcan 2006 Notes: P12				CO								
Delcan 2006 Notes: P12	Photo #	Domarke			21110		_					
P12 - Span 7 - stringer 1 rotten and beginning to crush - other stringers OK for now P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	r noto #		Notes:									
P05,P06 - Span 1 - stringers 2 and 8 split but OK for now P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	P12			and beal	nning to cr	ush - other	stringers OK for now	, 				
P03 - Open deck on DPG mainspans - 18 reject ties on mainspans Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description							<u> </u>					
Delcan 2005 Notes: - Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	• 						ans					
- Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description		 				<u> </u>						
- Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	l ———											
- Approaches OK - 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description												
- 18/99 reject ties (18%) - Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description	_	Delcan 20	D5 Notes:		_							
- Span 1 - stringers 2 and 8 split - Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description		- Approac	hes OK									
- Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description		- 18/99 re	ect ties (18%)		<u> </u>							
- Span 7 - Stringer 1 rotten Delcan 2004 Notes: P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description				8 split								
P01 - Approaches high P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description												
P03 - 17/99 reject ties (17%) P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description												
P04 - Ballast deck ties on approach spans poor P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description												
P12 - Span 1 - stringer 2 splitting vertically MAINTENANCE RECOMMENDATIONS Urgency Description												
MAINTENANCE RECOMMENDATIONS Urgency Description							_					
Urgency Description	P12	<u> - Span 1 -</u>										
				TENANCE	RECOMME	NDATION:	S					
1 year Replace stringer 1 - bents 6 to 8 - \$6,000												
	1 year											
	!	<u> </u>										
		<u> </u>										
		 -					_					
				- -								
		<u> </u>										

Greenville 88.20

		Brid	ge Inspect	on Report	-		24 T SEC.		
	2	Mid-Michigan R	Railway		-	- V	P-41		
	₹	Greenville	_						
		Michigan				Lui a			
Inspected	Ву:	Stan Reimer		DELCANI					
inspection	Date:	May 22, 2006	- DELCAN		A STATE OF THE STA				
Steel Struc	cture (Gird	ers/Beams)				1-33-14	1 - 171		
	iteel Tresti	Deck Typ	Ballast	Crossing	River	经经济的			
# Spans	17	Length	225	Access	Road				
# Tracks	1	Height		Flow Dir		Greenville 88	.20		
Year Built	1918		Alignment C			Flat River			
	General	G/F/P/B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B		
	Scour	Fair		Stringers	Good	Bridge Seats/Caps	Fair		
Cha	annel/Road	Fair	FI	oor Beams		Abuts/Backwalls	Fair		
	Approach	Fair	Girders	Truss/Slab		Piers, Towers, Bents	Fair		
	Deck	G/F/P/B	•	Top Flange		Misc	G/F/P/B		
Ties (C	pen Deck)	Good	Bot	om Flange		Guard Rail			
	ie Spacers		Web	/Diagonals		<u> </u>			
	Track	Good	Веап	ng Stiffners					
	Footwalk			Bracing	Fair				
	Handrail			Bearings		Overall Rating:	Fair		
			CO	MMENTS		<u> </u>			
Photo #	Remarks	- · · · · · · · · · · · · · · · · ·							
	Delcan 20								
P01-P03	- No chan	ge in condition	since 2005						
	- Since m	ajor repairs wer	e relatively	recent, det	tailed insp	ection of piles not yet	rqd		
_									
									
		. —							
	Delcan 20					_			
		ges since 2004	<u>inspection</u>						
	Delcan 20								
P01	- Approac	nes OK	I				_ — -		
P06					- siii biati	es at varying elevation	<u> </u>		
P05,P07		and 16 not repla ck - all ties are			lition	_			
_ <u></u>	UMA 2003		igar quiy ill	Soon could	<u> </u>		- - -		
			own 2 vear	s ago and r	epaired hy	y steel frame bents an	-		
	steel strin	gers. New deck.	All fair. No	action red	uired	, with			
				RECOMME		<u>s</u>			
Urgency	Descriptio								
- Gigano,	No action necessary								
	_								
									

Bridge Inspection Report Mid-Michigan Railway Greenville Michigan inspected By: Stan Reimer Inspection Date: May 22, 2006 Timber Trestle Structure with Steel Mainspan(s) Structure PT/Beam Deck Typ Open Crossing # Spans 17 Length 277 Access # Tracks 1 Height Flow Dir Flow Dir Greenville 8									
Greenville Michigan Inspected By: Stan Reimer Inspection Date: May 22, 2006 Timber Trestle Structure with Steel Mainspan(s) Structure PT/Beam Deck Typ Open Crossing River # Spans 17 Length 277 Access # Tracks 1 Height Flow Dir R - L Greenville 8									
Inspected By: Stan Reimer Inspection Date: May 22, 2006 Timber Trestle Structure with Steel Mainspan(s) Structure PT/Beam Deck Typ Open Crossing River # Spans 17 Length 277 Access # Tracks 1 Height Flow Dir R - L Greenville 8									
Inspected By: Stan Reimer Inspection Date: May 22, 2006 Timber Trestle Structure with Steel Mainspan(s) Structure PT/Beam Deck Typ Open Crossing River Access # Spans 17 Length 277 Access # Tracks 1 Height Flow Dir R - L Greenville 8									
Inspection Date: May 22, 2006 Timber Trestle Structure with Steel Mainspan(s) Structure PT/Beam Deck Typ Open Crossing River # Spans 17 Length 277 Access Road # Tracks 1 Height Flow Dir R - L Greenville 8									
Timber Trestle Structure with Steel Mainspan(s) Structure PT/Beam Deck Typ Open Crossing River # Spans 17 Length 277 Access Road # Tracks 1 Height Flow Dir R - L Greenville 8	1/2								
Structure PT/Beam Deck Typ Open Crossing River # Spans 17 Length 277 Access Road # Tracks 1 Height Flow Dir R - L Greenville 8	1 12								
# Spans 17 Length 277 Access Road Flow Dir R - L Greenville 8									
# Tracks 1 Height Flow Dir R - L Greenville 8									
Year Built ? Alignment T Flat Rive									
General G/F/P/B Superstructure G/F/P/B Substructure	≕								
Scour Fair Stringers Poor Bridge Seats/Caps									
Channel/Road Fair Floor Beams Abuts/Backwalls	Fair								
Approach Fair Girders/Truss/Slab Piers, Towers, Bents	Роог								
Deck G/F/P/B Top Flange Misc	G/F/P/B								
Ties (Open Deck) Fair Bottom Flange Guard Rai	i i								
Tie Spacers Fair Web/Diagonals	<u> </u>								
Track Fair Bearing Stiffners									
Footwalk Bracing									
Handrail Bearings Overall Rating:	Poor								
COMMENTS									
Photo # Remarks									
Delcan 2006 Notes:									
P08 - Span 1 sinkhole in ballast deck									
P06 - Stringer 1 in span 1 - recently replaced - new stringer width is less									
P11,P12 - Timber sill plates of bents 12 and 13 are on concrete slabs so not as urgent									
Delcan 2005 Notes:									
P02 - Bent 3 cap replaced	<u> </u>								
P03 - Span 1 - stringer 1 replaced									
P12 - Stringer 1 crushing over bent 16 (not bent 18)	_								
Delcan 2004 Notes:									
P01 - Approaches a bit low	-								
P03 - 0/28 reject ties (0%) for beam span									
P22,P23 - Ballast deck ties poor									
P04 - Sinkhole through ballast trough floor near bent 2									
P05,P06 - Span 1 - stringer 1 crushing and rotating out at bent 1 - to be replaced									
P09,P10 - Bent 3 pile cap crushing - urgent replacement									
P11 - Most bents are steel pipe piles with concrete pile caps - debris in river on rig	ht								
P12 - Stringer 2 from bents 3 to 5 - end rot									
P13 - Bent 5 - timber blocking on concrete caps is rotting									
P14 - Bent 13 - timber sill plate rotten and to be replaced									
P15 - Bent 14 - timber sill plate rotten and to be replaced									
P16,P17 - Bent 14 - pile cap starting to rot, post 4 is rotten and hollow									
MAINTENANCE RECOMMENDATIONS									
cy Description									
1 year Replace stringer 1 over bent 16 - \$5,000									
3 years Replace sill plates for bents 13 and 14 - \$10,000	"								
3 years Replace pile caps for bents 1, 14 and 15 - \$15,000									

	<u> </u>	Brid	ge Inspect	on Report				
		Mid-Michigan F	Railway				et on	
		Greenville					7	
XXLCN-898		Michigan					<u></u> 75	
Inspected		Stan Reimer		DELC	CAN	Þ		
Inspection		May 22, 2006						
	vay Structu			0	11			
Structure # Spans	OH Via 0	Deck Typ Length	-	Crossing Access	Hwy Road			
# Tracks		Height		Flow Dir	Roau	Greenville 89.31		
Year Built	7		Alignment T			Hwy. M-44 O/H Via		
	General		· · ·	rstructure	G/F/P/B	Substructure	G/F/P/B	
	Scour		СТР	Stringers		Bridge Seats/Caps		
Cha	annel/Road	Good	— — _{Fī}	oor Beams		Abuts/Backwalls		
j	Approach			Truss/Slab	Good	Piers, Towers, Bents	Good	
	Deck			Top Flange		Misc	G/F/P/B	
Ties (0	Open Deck)			tom Flange		Guard Rail		
	Tie Spacers			/Diagonals				
	Track			ng Stiffners			•	
	Footwalk	Good		Bracing				
	Handrail			Bearings		Overall Rating:	Fair	
			CO	MMENTS				
Photo #	Remarks							
	Delcan 20					_		
	- No chan	ge in condition	<u>since 2005</u>					
	ļ						_	
							- - -	
								
			— – -					
	-							
		_	' '					
						_		
	Delcan 20		_			<u> </u>		
		ge in condition	<u>since 2004</u>	<u> </u>				
D04	Delcan 20					_		
<u>P01</u>	UMA 2003	e deck on steel	<u> </u>			_		
	- Not insp			— – –	_		. — —	
	- HOL MOP		TENANCE	RECOMME	NDATION	8	-	
Urgency	Descriptio		LITARIOL	TAL GOITHING		<u> </u>		
Cigonoy	- Doodingto							
					_			
			_ -					
 	 							
			_					

	Bridge Inspection Report								
	~	Mid-Michigan R		ion Report			The Bang in		
	≷		allway	Comment of the same of					
	<i>></i>	Greenville							
		Michigan							
Inspected		Stan Reimer_		DELC	CAN				
Inspection		May 22, 2006					1		
Timber Tre	estle Struct						17年		
Structure	PT_	_ Deck Typ	Ballast	Crossing	Stream				
# Spans	6	_ Length	82	Access	Road R - L				
# Tracks	1	Height	— 	Flow Dir	Greenville 91.	.60			
Year Built	?	Alignment	Stream						
	General	G/F/P/B	Supe	erstructure	G/F/P/B	Substructure	G/F/P/B		
	Scour	Fair		Stringers	Fair	Bridge Seats/Caps	Poor		
Cha	annel/Road	Fair	F	loor Beams		Abuts/Backwalls	Fair		
ł	Approach	Fair	Girders	/Truss/Slab		Piers, Towers, Bents	Bad		
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B		
	Ties	Fair		tom Flange		Guard Rail			
-	re Spacers			/Diagonals					
	Track	Fair		ng Stiffners		-			
l ——	Footwalk	—— — —		Bracing	Fair	— — -			
-	Handrail			Bearings		Overall Rating:	Fair		
	i iai iuraii			MMENTS		U Overall Nauling.	1 (211		
51-4-4	D			MMEN (5					
Photo #	Remarks	NO NICHOLI				<u> </u>	_		
	Delcan 200				doss				
1		ge has urgent w		not been	aone		_ — —		
- <u>P</u> 04 P05		stumps 1 and 5		lles 4 E an		ionant renels and			
P05						ten - urgent repair rqd			
P09,P10		piles 1, 2, 3 and		st - ueeds u	aming too	<u>'</u>			
F09,F10	Delcan 200	ile <u>cap is rotten</u>	OII IGIL						
P03		stump 4 is rotte				_ 			
P04		piles 1, 2, 5 and		n frame h					
P07	- Bent 6	pile 1 is gone, p		nd 4 are pur	dir now				
P09-P10		<u>pile i is gone, p</u> pile cap rotten	1103 <u>2,</u> 3 al	in + ale bui	INY				
1034 10	Delcan 20								
P01	- Approac								
-~ ~ -		leck ties OK							
		piles 1, 2 and 5	are hollow	. piles 3 and	d 4 are pos	sted			
P07		Pile 4 complete		<u>, L a aı</u> ı,	<u>.~</u> P <u>oc</u>				
P08,P10		pile 3 is rotten r		lne, plie 2 is	s punkv				
P11		plie 1 is crushe							
P16,P18		pile cap split an							
P15		pile cap is split							
				RECOMME	NDATION	S			
Urgency									
	Frame bents 2, 4 and 5 - \$30,000								
1 year	Post bent 3 - pile 4, bent 4 - pile 3 - \$10,000								
1 year		ent 7 pile cap - \$							
-/		rogram - Bent 6		post 1					
		replacement wit							
	~~Q:WVI			420,000					

g*** (ion Report		ر مراجع		1	
 		Mid-Michigan F	Rallway			100	た。在文章	The second section is	
		Greenville				1. 1. 1	Section of the		
N 1 (1278)	Mary	Michigan				35 33	ന് എവ്യക്കുള്ള മാന്ധ്യക്കുള്ള		
Inspected		Stan Reimer			CAN	71.00	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Friedly	
Inspection	Date:	May 22, 2006				23.44	All Secus	100	
Culvert						3 10	一种技术	1.	
Structure	' x 12' RCI	Deck Typ	-	Crossing	Stream	17.8	で多たい。		
# Spans	1	Le <u>ng</u> th	13	Access	Road				
# Tracks	1	Height		Flow Dir	R-L		Greenville 91	.70	
Year Built	?	Alignment	T				Culvert		
	General		Supe	rstructure	G/F/P/B		Substructure	G/F/P/B	
	Scour	Fair		Stringers		Brid	ge Seats/Caps		
Cha	annel/Road	<u>Fair</u>		oor Beams			buts/Backwalls	Fair	
	Approach			/Truss/Slab	Fair		Towers, Bents		
	Deck	G/F/P/B		Top Flange		Misc		G/F/P/B	
	Deck)			tom Flange		_	Guard Rail		
l <u> </u>	Tie Spacers			/Diagonals		i			
	<u>Trac</u> k	Fair	Bean	ng Stiffners					
	Footwalk			Bracing	_				
	Handrail			Bearings		Ove	rall Rating:	Fair	
			CO	MMENTS					
Photo #	Remarks								
	Delcan 20								
P01-P04	- No chan	ge in condition	since 2005	j					
	<u> </u>			<u> </u>			_ _		
	! .								
	<u> </u>			_					
								- 	
— –	 		_ _ -			- -	_		
	<u> </u>								
	Delcan 20	NE Natas:			- - -		-		
		ge in condition	eince 2004	_					
	Delçan 20		511100 2007	*	<i>_</i>				
P01	- Approac								
P06		ndition but ove	rgrown _				_		
	UMA 2003		<u></u>				_	_	
	- Not insp	ected							
		MAIN	TENANCE	RECOMME	NDATION	S			
Urgency	Description	n							
	No action necessary								
							_		
	 _						_		
	<u> </u>						_ _		
_	L								

**************************************			ge Inspect] ,		
—)2		Mid-Michigan R	lailway		•	Mix a.		
		Greenville						
	A SALES CONTRACTOR	Michigan				HARLING TO THE PARTY OF THE PAR		
Inspected		Stan Reimer			ZANI	Karana A	14 (11 + + + + + + + + + + + + + + + + + +	
Inspection		May 22, 2006				了。 第二章	10 N 10	
		ers/Beams)						
	on Bridge		ļ.	Crossing	Stream	(b) halify (high property)	in the state	
# Spans	0	Length	0	Access	Road			
# Tracks	1	Height		Flow Dir		Greenville 94		
Year Built	?	Alignment	T		0:5/5/5	Road Bridge		
	General	G/F/P/ <u>B</u>	Supe	rstructure	G/F/P/B_	Substructure	G/F/P/B	
	Scour			Stringers		Bridge Seats/Caps		
Cha	annel/Road			oor Beams		Abuts/Backwalls		
=	Approach			Truss/Slab		Piers, Towers, Bents	0.15.15.15	
	Deck			Top Flange		Misc	_G/F/P/B	
)pen Deck)			tom Flange		Guard Rail		
1	Tie <u>Spacers</u>			/Diagonals				
	Track		Bean	ng Stiffners				
	Footwalk			Bracing	-,-			
	Handrail			Bearings		Overall Rating:	Poor	
			co	MMENTS				
Photo #	Remarks							
_ :	Delcan 20				***			
P03	- Timber t	bearing blocks t	<u>or rail st</u> rin	gers are ro	tting at en	ds - OK for now		
	 -					_ <u> </u>		
<u> </u>	 -					_		
				 -				
_	Delcan 20	05 Notes:						
		ge in condition	since 2004	 -				
-	Delcan 20				 -		-	
P01	- This is a	road bridge ad	acent to a	nd crossing	the tracks			
P04		ructure is steel i						
		r closing this br						
		se, consider rep		a culvert y	vhen bridg	e starts to fail		
P01		s posted for 15 t	ons			<u> </u>		
	UMA 2003					<u> </u>		
	- Not insp							
-	<u> </u>		TENANCE	RECOMME	NDATION!	<u> </u>		
Urgency	Descriptio					<u> </u>		
- —	No action	<u>necessary</u>				_		
		-				-		
- 								
- -						-	 -i	
_						_		
· ——								
	l ———					-		

		Bridge Inspection Report									
	~			ion Report		The second second	A Section				
	>	Mid-Michigan R	allway								
		Greenville				- Target 197	- 17				
		Michigan									
Inspected		Stan Reimer			CAN		11,				
Inspection		May 22, 2006	22, 2006			the state of the s					
	stle Struct					1 19th 14 "	31 T				
Structure	<u> </u>	Deck Typ	Ballast	Crossing	Stream	1 1 1 1 2 2 2 2	a e				
# Spans	<u> </u>	_ Length	13	Access	< 1/2 mile						
# Tracks	1	<u>Height</u>	<u>,- </u>	Flow Dir	RL	Greenville 95.					
Year Built	1929	Alignment	T	_		Cattle Pass					
	General	G/F/ <u>P</u> /B	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B				
	Scour			Stringers	Poor	Bridge Seats/Caps	Fair_				
Cha	annel/Road			loor Beams		Abuts/Backwalls	Fair				
	Approach	Fair	Girders/	Truss/Slab		Piers, Towers, Bents	Poor				
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B				
	Ties	Fair	Bot	tom Flange		Guard Rall					
<u> </u>	ie Spacers			/Diagonals							
	Track	Fair	Bean	ng Stiffners							
	Footwalk			Bracing							
	Handrail			Bearings		Overall Rating:	Poor				
			CO	MMENTS	-		-				
Photo #	Remarks	_									
	Delcan 20	06 Notes:									
P05		5 rotten at bent	1								
P06		ap rotten on left									
		lles 2 and 4 are		3 is poste	<u> </u>						
	Delcan 20										
P08	- Stringer	5 is rotten									
P03-P04		ile cap rotten									
P05		piles 2 and 4 are	hollow								
	Delcan 20										
P <u>01</u> _	- Approac										
P03		leck ties OK									
P06		piles 2 and 4 ho					,				
P04,P07		ap starting to ro	t <u>on</u> left								
	UMA 2003			_							
						ted on left side. 9-8x16	I				
			iollow at to	p. riie 3 is	posted. B	ent 1 needs to be					
<u> </u>	irramed Wi	thin 3 years.		2222	MBASS						
<u> </u>			IENANCE	RECOMME	NUATION	<u> </u>					
	Descriptio					<u> </u>					
<u>5 years</u>	Replace Stringers \$10,000										
<u> </u>	 										
– –––	 										
<u> </u>	<u> </u>					_ _	— - [
<u> </u>	-	-		<u> </u>		 					
I- ——											
<u> </u>											

ALL DE CO				ion Report			这 洲连			
		Mid-Michigan R	lailway				学 學學			
		Greenville					设建 护设置			
-	Mark 1	Michigan					600			
Inspected Inspection		Stan Reimer May 22, 2006		DEL	CAN					
Culvert	Date.	May 22, 2000				いるという	建产业			
	6' x 8' RCE	Deck Typ		Crossing	Stream	思维。				
# Spans	0 10 KCB	Length	0	Access	< 1/2 mile	が治します。対してい	3 4			
# Tracks	1	Height	<u>~</u> _	Flow Dir	R-L	Greenville 98.	00			
Year Built		Alignment				Culvert				
	General		Supe	rstructure	G/F/P/B	Substructure	G/F/P/B			
	Scour	Fair		Stringers	<u> </u>	Bridge Seats/Caps	·			
Cha	annel/Road	Fair	FI	oor Beams		Abuts/Backwalls	— Fair			
	Approach	Fair	Girders/	Truss/Slab	Fair	Piers, Towers, Bents				
	Deck	G/F/P/B	-	Top Flange		Misc	G/F/P/B			
Ties (C)pen Deck)		Bot	tom Flange		Guard Rail				
	ie Spacers		Web	/Diagonals						
	Track	Fair	Bean	ng Stiffners						
	Footwalk			Bracing						
	Handrail			Bearings		Overall Rating:	Fair			
	<u> </u>		CO	MMENTS						
Photo #	Remarks					<u> </u>				
	Delcan 200			<u>_</u>						
P01-P04		ge in condition	<u>since 2005</u>	l .						
	- Özelðlö	wn with brush								
							— <u> </u>			
		-								
	 -	<u> </u>			. — –					
	Delcan 20									
<u> </u>		ge in condition	<u>since 2004</u>			_				
P01	Deican 200 - Approac				- - -					
P02		alling in headw	all of outle	t on left						
	UMA 2003		<u>un oi ou io</u>	. 011 1011	,					
	- Not insp									
			TENANCE	RECOMME	NDATIONS	<u> </u>				
Urgency	Descriptio									
	No action									
	-									
<u> </u>							— <i>—</i> [
	<u> </u>	_ — —								
	I									

	'510's	Brid	ge Inspect	ion Report	-				
 	3 :	Mid-Michigan R	Railway						
	* `	Greenville	-				4		
,	a 12 m	Michigan					1		
Inspected		Stan Reimer		mei (
Inspection		May 22, 2006	DELCAN				. 多篇		
Timber Tro	estle Struc	ture					1997		
Structure	PT	Deck Typ.	Ballast	Crossing	Stream	是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个			
# Spans	1 _1 _	Length	13 Access < 1/2 mile						
# Tracks	1	Height	Flow Dir R - L.		Greenville 99.	50			
Year Built	1929	Alignment	T			Cattle Pass			
	General		Supe	rstructure	G/F/P/B	Substructure	G/F/P/B		
	Scour	Fair		Stringers	<u>Fair</u>	Bndge Seats/Caps	Fair		
Cha	annel/Road	<u>Fair</u>		oor Beams		Abuts/Backwalls	Fair		
	Approach	Fair		Truss/Slab		Piers, Towers, Bents	Poor		
	Deck		·	Top Flange		Misc	G/F/P/B		
	Ties	Fair		tom Flange		Guard Rail			
	le Spacers			/Diagonals					
	Track	Fair	Bean	ng Stiffners					
	Footwaik			Bracing					
	Handrail			Bearings		Overall Rating:	Fair		
			CO	MMENTS					
Photo #	Remarks								
	Delcan 20					_			
P01-P05	- No chan	ge in condition	since 2005						
	l — —								
	 -								
									
		_							
	 -								
	Delcan 20	05 Notes:							
		ge in condition	since 2004						
	Delcan 20				-	•			
P01	- Approac	hes OK							
P03	- Ballast o	leck ties OK							
P06		pile 3 split and 1	o be band	ed					
	UMA 2003			-					
	9 <u>-8x1</u> 6 str	nge <u>rs. Bent 2 p</u>	lie 1 needs	to be on p	lan to post	. Both caps are fair.			
	Ballast cu	rbs are tipping.							
			TENANCE	RECOMME	NDATION	<u> </u>			
Urgency									
	Banding program - bent 2, pile 3								
	 								
									
	 								
							· -		
									
	l — —					_			

		D-11	1	B		in the spreading of the company				
		Bridge Inspection Report				A STANDARD				
		Mid-Michigan Railway								
	>	Greenville Michigan								
Inspected	Rv.	Stan Reimer		I		Charles and the second				
Inspected By: Inspection Date:		May 22, 2006			CAN	10 m	10 1483			
	estle Struc					经验以	自己的			
Structure	PT									
# Spans	1	Length	13	Crossing Access.	< 1/2 mile	A STATE OF THE PARTY OF THE PAR	D-27, 21, 42, 42, 52, 52			
# Tracks	1	Height	- 13	Flow Dir	R-L	Greenville 99.	80			
Year Built	1929/50	Alignment	T	FIOW DII	K-L	Cattle Pass				
Teal Duilt					G/F/P/B	Substructure	G/F/P/B			
	General		Supe	rstructure						
٥.	Scour		Stringers		Poor	Bridge Seats/Caps	Fair _			
Cha	annel/Road		Floor Beams Girders/Truss/Slab			Abuts/Backwalls	Fair			
	Approach					Piers, Towers, Bents	Bad			
	Deck			Top Flange		Misc	G/F/P/B			
	Ties	Fair	Bottom Flange			Guard Rail				
	ie Spacers			n/Diagonals						
	Track	Fair	Bean	ng Stiffners						
	Footwalk			Bracing						
Handrail			Bearings			Overall Rating:	Poor			
			CC	MMENTS						
Photo #	Remarks									
	Delcan 20					<u> </u>				
P04,P06										
P05	- Bent 1 -	piles 1, 2, 4 and	5 are hollo	w and/or r	otten - nee	ds framing_				
	Delcan 20									
P05,P06		1 and 9 are rott								
_ P04		piles 1, 2, 4 and	5 are holic	ow						
	Delcan 20									
P01	- Approac									
P02		deck ties OK								
P04 P05		pile 5 hollow				 				
P06,P07		pile 4 punky s discolored, st	ringer P et	ortina to sof	<u> </u>					
FU0,FU/	UMA 2003		miña, a an	nung to ro	.					
			nt 2 nlla 4	le had: 2 A	2 5 are he	illow: 3 le feir: 6 le coli	d - J			
	Bent 1 pile 4 is hollow. Bent 2 pile 1 is bad; 2, 4 & 5 are hollow; 3 is fair; 6 is solid. Stringer 9 is hollow. Bent 2 needs to be framed within 1 year.									
MAINTENANCE RECOMMENDATIONS										
Urgency										
1 year 3 years										
o years	rs Replace 2 stringers - \$10,000									
	-									
										
										
										

R		Bridge Inspection Report						ا المنطقة		
		Mid-Michigan Railway					المنظيمية منصوص [ال			
		Greenville				4				
		Michigan				7				
Inspected By:		Stan Reimer	_	DELCAN		, A.	Single Single	7.3440		
Inspection	Date:	May 22, 2006		المناجع ليهبا		l 	한화 것 ·			
Culvert						1. 4 . 4 .	·	y 4-1		
Structure	CMP	Deck Typ		Crossing	Stream		34 (35)			
# Spans	0	Length	. 0	Access	Road					
# Tracks	<u> 1</u>	Height		Flow Dir	R-L	Greenville 99.85		85		
Year Built		Alignment		T		Culvert				
	General		Supe	rstructure	G/F/P/B		Substructure	G/F/P/B		
	Scour	Fair	Stringers Stringers			Bridge Seats/Caps		- <u>-</u> . —		
Cha	annel/Road	Fair		oor Beams	Fair		outs/Backwalls	Fair		
	Approach	Fair	Girders/Truss/Slab		Pair		Towers, Bents	C/E/D/D		
	Deck	G/F/P/B	Top Flange			Misc		G/F/P/B		
	pen Deck)			tom Flange			Guard Rail			
!	ie Spacers Track	Fair		/Diagonals						
	Footwalk	Fair	beam	ng Stiffners Bracing		-				
	Handrail			Bearings		Ove	rall Rating:	Fair		
	i igrigigii		CO	COMMENTS			an reality.	1 400		
Photo #	Remarks			MINIELT I Q				·		
r iioto #	Delcan 20	06 Notes:	.			-				
		ge in condition	since 2005							
		<u>a </u>	<u> </u>							
-										
							-			
	-		_							
										
	Delcan 20	Notes:								
		ge in condition	since 2004				•			
	Delcan 20				-		·			
P01	- Approac							· ·. <u>_</u>		
	- Pipe culvert									
	UMA 2003									
- Not inspected										
MAINTENANCE RECOMMENDATIONS										
Urgency Description										
	No action necessary									
	 									
— 	—	_								
					-		-	-		

Ex. Chambri	***	Bride	ne inepact	ion Report		,				
		Mid-Michigan R			J. Link					
		Greenville	aliway			A Commence of the Commence of	2			
2772		Michigan					The state of			
Inspected	Rv:	Stan Reimer					一门外			
Inspection Date:		May 22, 2006		DELCAN			- 011-			
Culvert		,,				Marie Control	الشاسرا			
Structure	CMP	Deck Typ -		Crossing Stream		the state of the s	第 44			
# Spans	- 0	Length	0	Access	Road		<u> </u>			
# Tracks	-	Height		Flow Dir	R-L	Greenville 99	90			
Year Built	7	Alignment				Culvert				
	General	. —	Supe	rstructure	G/F/P/B	Substructure	G/F/P/B			
	Scour		Stringers			Bndge Seats/Caps				
Cha	annel/Road			loor Beams	 -	Abuts/Backwalls	Fair			
	Approach			/Truss/Slab	Fair	Piers, Towers, Bents				
	Deck			Top Flange		Misc	G/F/P/B			
Ties (C)pen Deck)			tom Flange		Guard Rail				
	Tie Spacers			/Diagonals						
	Track			ng Stiffners						
	Footwalk		Bracın							
	Handrail			Bearings		Overall Rating:	Fair			
	<u> </u>		CO	MMENTS						
Photo #	Remarks									
	Delcan 200									
- No change in condition since 2005										
ļ	<u> </u>									
	- —									
						 -				
	Delcan 200	05 Notes:								
		ge in condition	since 2004							
-	Delcan 200									
P01	- Approac									
	- Pipe cul	vert								
	UMA 2003	Notes:								
	- Not inspected									
MAINTENANCE RECOMMENDATIONS										
Urgency Description										
No action necessary										
	— — — — — — — — — — — — — — — — — — —									
	-									
	 									
 -	- <i>-</i> -									

Greenville 103.00

		Bridge Inspection Report							
		Mid-Michigan Railway				建建设的			
		Greenville							
		Michigan					77		
Inspected By: Inspection Date:		Stan Reimer May 22, 2006		DELCAN					
Culvert									
Structure	CMP	Deck Typ		Crossing	Stream				
# Spans	0	Length	0	Access	< 1/2 mile	and to his in the second stay of the			
# Tracks		Height		Flow Dir	L-R	Greenville 10	3.00		
Year Built	7	Alignment	T			Culvert			
	General		Superstructur		G/F/P/B	Substructur	G/F/P/B		
	Scour	Fair	Stringers			Bridge Seats/Cap	s		
Cha	annel/Road	Fair	F	loor Beams		Abuts/Backwall			
	Approach	Fair	Girders	/Truss/Slab	Fair	Piers, Towers, Bent	S		
	Deck	G/F/P/B		Top Flange		Misc	G/F/P/B		
Ties (C	Den Deck)		Bot	tom Flange		Guard Ra	il		
	le Spacers		Web	/Diagonals					
	Track	_. Fair	Веал	ng Stiffners					
	Footwalk		11	Bracing			<u>i </u>		
	Handrail		Bearings			Overall Rating:	Fair		
			CO	MMENTS					
Photo #	Remarks								
	Delcan 200								
P01-P04	- No chan	ge in condition	since 2005						
			_						
	Delcan 200								
		ge in condition	since 2004	ı					
P01	Delcan 200								
-VI	- Approaches OK - Twin pipes								
	UMA 2003 Notes:								
	- Not inspected								
MAINTENANCE RECOMMENDATIONS									
Urgency Description									
	No action								
							-		
———									